Preventive Maintenance Checklist - Servo Press SP-04

Document ID	MAINT-CHK-007
Inspection date	2026-09-15
Shift	1
Technician	Synthetic Operator M01
Language	English

Equipment information

Machine: Servo Press SP-04 | Location: Line A3 | Asset ID: PRS-A3-04

Preventive maintenance checklist

Check item	Frequency	Standard / limit	Result	Status
Air pressure	Daily	0.50-0.60 MPa	0.56 MPa	OK
Safety light curtain	Daily	Machine stops when beam is interrupted	Pass	OK
Ram home repeatability	Weekly	≤ 0.05 mm	0.03 mm	OK
Upper die lubrication	Weekly	Thin continuous film; no dry surface	Applied	OK
Servo motor temperature	Monthly	< 65 °C	58 °C	OK
Main filter differential pressure	Monthly	< 0.12 MPa	0.09 MPa	OK

Abnormality action

- If air pressure is outside 0.50-0.60 MPa, stop automatic operation and check the regulator and upstream supply.
- If servo motor temperature reaches 65 °C or higher, stop the machine and contact Maintenance.
- Record replaced parts in the maintenance history with machine ID and downtime.