

Vehicle Diagnostic Report

The Report is created by **LAUNCH X-431**

Vehicle Information

Year:2008
Make:GM
Model:Yukon XL
VIN:1GKFK16368J144884
Vehicle Software Version:V50.35
Diagnostic Application Version:V8.00.037
Diagnostic path:Automatically Search



Repair Shop

Shop Name:BC
Address:
Zip Code:
Telephone:
Email:
SN:989347712041
Test Time:2026-03-14 08:14:42



System fault code 【Pre-Repair】

The following systems is abnormal:

Driver Door Switch (DDS)

DTC (1)

1.B2555-01 Passenger Compartment Lamp Control Circuit Short To Battery

Last Test:Passed
Since Cleared:Passed

HVAC Control Module (HVACCM)

DTC (1)

1.B3779-05 Air Flow Control 9 Feedback Circuit Short To Battery Or Open

Park Assist Module (PAM)



DTC (1)

1.B0958-06 Parking Aid Rear Sensor 1 Circuit Short To Ground Or Open Last Test:Failed/Current

Passenger Door Switch (PDS)

DTC (1)

1.B2555-01 Passenger Compartment Lamp Control Circuit Short To Battery	Last Test:Passed Since Cleared:Passed
Remote Control Door Lock Receiver (RCDLR)	
DTC (3)	
1.C0750-00 Left Front Low Tire Pressure Sensor	Last Test:Passed Since Cleared:Passed
2.C0760-00 Left Rear Low Tire Pressure Sensor	Last Test:Passed Since Cleared:Passed
3.C0765-00 Right Rear Low Tire Pressure Sensor	Last Test:Passed Since Cleared:Passed
Supplemental Inflatable Restraint (SIR)	
DTC (7)	
1.B0012-0E Driver Steering Wheel Air Bag Deployment Loop Resistance Below Threshold	Last Test:Failed/Current This Ignition:Not Run/Fail Since Cleared:Not Run/Fail
2.B0015-04 Driver Pretensioner Deployment Loop Open Circuit	Last Test:Failed/Current This Ignition:Not Run/Fail Since Cleared:Not Run/Fail
3.B0022-04 Passenger Pretensioner Deployment Loop Open Circuit	Last Test:Failed/Current This Ignition:Not Run/Fail Since Cleared:Not Run/Fail
4.B0015-0D Driver Pretensioner Deployment Loop Resistance Above Threshold	Last Test:Passed This Ignition:Passed Since Cleared:Passed
5.B0022-01 Passenger Pretensioner Deployment Loop Short To Battery	Last Test:Passed This Ignition:Passed Since Cleared:Passed
6.B0090-71 Rollover Sensor Performance Invalid Serial Data Received	Last Test:Passed This Ignition:Passed Since Cleared:Passed
7.U0172-00 Lost Communication With Restraints System Sensor C	Last Test:Passed This Ignition:Passed Since Cleared:Passed

The following systems are OK:

- 1.Body Control Module (BCM)
- 2.Digital Radio Receiver (DRR)
- 3.Instrument Panel Cluster (IPC)
- 4.Passenger Presence System (PPS)
- 5.Radio (RADIO)
- 6.Rear Heating Ventilation And Air Conditioning (RHVAC)/Rear Seat Audio (RSA)
- 7.Rollover Sensor (RS)
- 8.Theft Deterrent Module (TDM)
- 9.Vehicle Communication Interface Module (VCIM)

This test report is for reference only for vehicle test and maintenance. The vehicle operating data provided in this report are all static data. The detailed dynamic diagnostic data can be read by professional maintenance device, and LAUNCH will not be liable for any accidents and failures arising therefrom!