

Vehicle Diagnostic Report

The Report is created by **LAUNCH** X-431

Vehicle Information

Year:2008
Make:GM
Model:Yukon XL
VIN:1GKFK16368J144884
Vehicle Software Version:V50.35
Diagnostic Application Version:V8.00.037
Diagnostic path:Automatically Search



Repair Shop

Shop Name:BC
Address:
Zip Code:
Telephone:
Email:
SN:989347712041
Test Time:2026-03-14 08:17:24



System fault code 【Pre-Repair】

The following system is abnormal:

Supplemental Inflatable Restraint (SIR)

DTC (3)

1.B0012-0E Driver Steering Wheel Air Bag Deployment Loop Resistance Below Threshold

Last Test:Failed/Current
This Ignition:Not Run/Fail
Since Cleared:Not Run/Fail

2.B0015-04 Driver Pretensioner Deployment Loop Open Circuit

Last Test:Failed/Current
This Ignition:Not Run/Fail
Since Cleared:Not Run/Fail

3.B0022-04 Passenger Pretensioner Deployment Loop Open Circuit

Last Test:Failed/Current
This Ignition:Not Run/Fail
Since Cleared:Not Run/Fail

The following systems are OK:

- 1.Body Control Module (BCM)
- 2.Digital Radio Receiver (DRR)
- 3.Driver Door Switch (DDS)
- 4.HVAC Control Module (HVACCM)
- 5.Instrument Panel Cluster (IPC)

6.Park Assist Module (PAM)



7.Passenger Door Switch (PDS)

8.Passenger Presence System (PPS)

9.Radio (RADIO)

10.Rear Heating Ventilation And Air Conditioning (RHVAC)/Rear Seat Audio (RSA)

11.Remote Control Door Lock Receiver (RCDLR)

12.Rollover Sensor (RS)

13.Theft Deterrent Module (TDM)

14.Vehicle Communication Interface Module (VCIM)

Disclaimer

This test report is for reference only for vehicle test and maintenance. The vehicle operating data provided in this report are all static data. The detailed dynamic diagnostic data can be read by professional maintenance device, and LAUNCH will not be liable for any accidents and failures arising therefrom!