

## Vehicle Diagnostic Report

The Report is created by **LAUNCH** X-431

### Vehicle Information

Year:2008  
Make:GM  
Model:Yukon XL  
VIN:1GKFK16368J144884  
Vehicle Software Version:V50.35  
Diagnostic Application Version:V8.00.037  
Diagnostic path:Automatically Search > Engine Control Module (ECM)



### Repair Shop

Shop Name:BC  
Address:  
Zip Code:  
Telephone:  
Email:  
SN:989347712041  
Test Time:2026-03-14 08:04:40



### DTC 【Pre-Repair】

| DTC      | Description                                 | State                                                                     |
|----------|---------------------------------------------|---------------------------------------------------------------------------|
| P0121-00 | Throttle Position (TP) Sensor 1 Performance | Last Test:Not Run<br>This Ignition:Not Run<br>Since Clear:Passed & Failed |
| P0300-00 | Engine Misfire Detected                     | Last Test:Passed<br>This Ignition:Not Run<br>Since Clear:Passed & Failed  |
| P0513-00 | Theft Deterrent Key Incorrect               | Last Test:Passed<br>This Ignition:Passed<br>Since Clear:Passed & Failed   |
| P0633-00 | Theft Deterrent Key Not Programmed          | Last Test:Passed<br>This Ignition:Passed<br>Since Clear:Passed & Failed   |

|          |                                                  |                                                                                  |
|----------|--------------------------------------------------|----------------------------------------------------------------------------------|
| P1380-00 | Misfire Detected - Rough Road Data Not Available | Last Test:Failed/Current<br>This Ignition:Not Run<br>Since Clear:Passed & Failed |
| P1631-00 | Theft Deterrent Fuel Enable Signal Not Correct   | Last Test:Passed This<br>Ignition:Passed<br>Since Clear:Passed & Failed          |

.....

**Disclaimer**

This test report is for reference only for vehicle test and maintenance. The vehicle operating data provided in this report are all static data. The detailed dynamic diagnostic data can be read by professional maintenance device, and LAUNCH will not be liable for any accidents and failures arising therefrom!