

Vehicle Diagnostic Report

The Report is created by **LAUNCH X-431**

Vehicle Information



Year:2011

Make:TOYOTA

Model:Tacoma

VIN:5TFUU4EN2BX005907

Engine Size:1GR-FE 4.0L 6 Dual Overhead Cam (DOHC)

Vehicle Software Version:V51.50

Diagnostic Application Version:V8.00.031

Diagnostic path:Automatic Search > North America > Tacoma > 2011 > 1GR-FE > Vacuum Type VSC

Repair Shop

Shop Name:

Address:

Zip Code:

Telephone:

Email:

SN:989347712041

Test Time:2026-01-07 13:47:45



System fault code 【Pre-Repair】

The following system is abnormal:

TPMS (Tire Pressure Monitoring System)

DTC (5)

1.C2121 Cannot Receive a Data from the Transmitter ID1 (Main)	Current
2.C2122 Cannot Receive a Data from the Transmitter ID2 (Main)	Current
3.C2123 Cannot Receive a Data from the Transmitter ID3 (Main)	Current
4.C2124 Cannot Receive a Data from the Transmitter ID4 (Main)	Current
5.C2173 Vehicle Speed or Engine Speed Signal Error	Current

The following systems are OK:

1.EOBD/OBD II

2.ECMECT (Engine and ECT)

3.CCS (Cruise Control)



4.ABS (Anti-lock Braking System)/VSC (Vehicle Stability Control)/TRAC (Traction Control System)

5.SRS (Supplemental Inflatable Restraint System)

6.OD (Occupant Detection)

7.IMMO (Immobiliser)



Disclaimer

This test report is for reference only for vehicle test and maintenance. The vehicle operating data provided in this report are all static data. The detailed dynamic diagnostic data can be read by professional maintenance device, and LAUNCH will not be liable for any accidents and failures arising therefrom!