



H/W = 0.0

mean 42.6%, range 5.92




H/W = 0.5

mean 26.1%, range 4.74



H/W = 1.0

mean 13.5%, range 3.49



H/W = 1.5

mean 7.7%, range 2.53

