






Power On Button



Reset Button








NOTES


- 1. Connect 5V, 3A power supply through Micro USB-C
- 2. Do not change the 47uF Capacitor Package. Value can be increased if needed.
- 3. PMIC Power on. Internal Pull up present within SiP


Sheet: /Power & Reset/ File: Power & Reset.sch	
Title: Power & Reset	
Size: A4 Date: 2021-05-18	Rev: 1.0.0
KiCad E.D.A. kicad (5.1.10-1-10_14)	ld: 2/10

















DSI LCD




RPi Expansion Header



Snap Connectors







Sheet: /Connectors/ File: Connectors.sch

Title: Snap	Connectors


Size: A4	Date: 2021-05-18	Rev: 1.0.0
KiCad E.D.A. k	icad (5.1.10-1-10_14)	ld: 9/10

Push Button






LEDs



BOOT CONFIGURATION





	Sheet: /Boot Config, LED & Button/ File: Boot Config, LED & Button.sch		D	
Title: Boot Config, LEDs & Buttons				
	Size: A4 Date: 2021-05-18 KiCad E.D.A. kicad (5.1.10-1-10_14)	Rev: 1.0.0 Id: 10/10		