8180

Required field (x) was not populated by (y).

x = Field name

y = Remote system

Probable cause

Corrective action

Mandatory ASTM field was blank in the message received. The remainder of the message is ignored by the system.

For host:

 Incorrectly formatted record or message received from the host. Refer to the ARCHITECT System Abbott Standard Interface RS-232 Manual.

For ARM:

· Software error.

Contact your Area Customer Support. Please provide information about the operation you were attempting to perform when the error occurred.