PP1SI-01

RECOMMENDED TOOLS

	09042-00010	Torx Socket T30 .	
	09042-00020	Torx Socket T40 .	
	09050-20010	Air Riveter.	
	(09050-02010)	Dust Cap.	
0)	(09050-02030)	Nose Piece No.2.	
	09050-00032	Air Drill	
	(09050-00210)	Chuck Set	
	(09050-00220)	Handle	
	09060-60350	Revet Cutter.	
Transfer	09070-20010	Moulding Remover .	