DIASC-01

DTC	C1532 / 32	VGRS ECU Malfunction
-----	------------	----------------------

CIRCUIT DESCRIPTION

DTC No.	DTC Detecting Condition	Trouble Area
C1532/32	The system detects a malfunction inside the ECU.	•VGRS ECU

INSPECTION PROCEDURE

1	Check for other VGRS DTCs.
---	----------------------------

CHECK:

Are there any other VGRS DTCs?



YES

2 Perform troubleshooting for remaining DTCs.

NEXT

After repairing other DTCs, if C1532/32 still exists, replace VGRS ECU.