RECOMMENDED TOOLS

PP1AO-05

			1
	09042-00010	Torx Socket T30 .	
	09042-00020	Torx Socket T40 .	
	09050-20010	Air Riveter.	
	(09050-02010)	Dust Cap.	
	09050-02050	Nose Piece No.4.	
	09050-00032	Air Drill	
	(09050-00210)	Chuck Set	
	(09050-00220)	Handle	
	09060-60350	Revet Cutter.	
and the second	09070–20010	Moulding Remover .	