DIONAL OC

8. Color on havigation screen is unusual (RGB signal error).

INSPECTION PROCEDURE	
1[]	Display[check[mode[(Color[bar[check).
	NG Replace the multidisplay.
2	Navigation[check[mode](Color[bar[check).
	NG∐ Go[to[step[4.
ОК	
3[]	Check[the[screen[setting.[Day[or[Night[mode)
	OK Normal.
NG	
4	Check[the[navigation[ECU[power[source[circuit[(see[page[DI-256).
	NG Replace or repair wire harness or connector.
ок	

5 Check[the[display]signal[circuit[[see[page[DI-270]].

NG

Replace or repair wire harness or connector.

OK

Replace the multi-display.