
TERMINALS OF ECU





Symbols[[Terminals[]No.)	Wiring@Color	Condition	STD[Voltage[[V)
BATT[[E14 -[]]) -[E1[[E13 -[]4]	B-R[↔[₿R	Always	9[}-[]4
+[B[[E14 -[]2] -[E1[[E13 -[]4]	B–Y[⊷[BR	IG[switch[DN	9[}-[]4
VC[[E12 -[]]) -[E2[[E12 -[9]]	L-R[+→[BR-W	IG[switch[DN	4.5[-]5.5
VTA[[E12 -[]1]]-[E2[[E12 -[9)	R=Y[→[BR=W	IG[switch[ON Throttle[yalve[fully[closed	0.3[]-[].0
		IG[switch[DN] Throttle[yalve[fully[open]	3.2∏-[4.9
	D=1 =	Always IG[switch[ON] IG[switch[ON] IG[switch[ON] Throttle[valve[dully[closed]] IG[switch[ON]	3.3[}[3.9
PIM[[E12 -[2]) -[E2[[E12 -[9])	P=L[→[BR=W	Apply[yacuum[26.7[kPa[[200[]nmHg,[7.9[]n.Hg)	2.5[}[3.1
THA[[E12 -[3]) -[E2[[E12 -[9])	Y–B[↔[BR–W	Idling,[]ntake[air[]emp.[20°C[[68°F]]	0.5[}-[3.4
THW[[E12 -[4]) -[E2[[E12 -[9])	G-B[↔[BR-W	Idling,[Engine[coolant]]emp.[80°C[[176°F]]	0.2[]-[].0
STA[[E14 -[]1]]-[E1[[E13 -[]4)	B-R[↔[BR	Cranking	6.0[pr[more
	Y ↔ W-B	IG[switch[DN	9[-] 4
#10[[E12 -[]2) - E01 (E13 - 13)		Idling	Pulse generation (See page DI-75)
	G ↔ W-B	IG switch ON	9 ~ 14
#20 (E12 – 11) – E01 (E13 – 13)		Idling	Pulse generation (SeepageDI-75)
#30 (E12 – 25) – E01 (E13 – 13)	Y-B ↔ W-B	IG switch ON	9 ~ 14
		Idling	Pulse generation (SeepageDI-75)
IGT1 (E13 – 20) – E1 (E13 – 14)	B ↔ BR	Idling	Pulse generation (SeepageDI-68)
IGT2 (E13 – 19) – E1 (E13 – 14)	R ↔ BR	Idling	Pulse generation (SeepageDI-68)
IGT3 (E13 –1 8) – E1 (E13 – 14)	L ↔ BR	Idling	Pulse generation (SeepageDI-68)
	B-W ↔ BR	IG switch ON	Below 2.0
IGF1 (E13 – 3) – E1 (E13 – 14)		Idling	Pulse generation (SeepageDI-68)
SIL (E12 – 10) – E1 (E13 – 14)	V–W ↔ BR	During transmission	Pulse generation
TACH (E13 – 8) – E1 (E13 – 14)	B ↔ BR	Idling	Pulse generation
G2 (E13 – 5) – NE– (E13 – 17)	R ↔ G	Idling	Pulse generation (SeepageDI-50)

DIAGNOSTICS - ENGINE

Symbols (Terminals No.)	Wiring Color	Condition	STD Voltage (V)
NE+ (E13 - 4) - NE- (E13 - 17)	L⇔G	Idling	Pulse generation (See page DI-50)
FC (E14 - 4) - E1 (E13 - 14)	B-W ↔ BR	IG switch ON	9 ~ 14
RSD (E13 – 10) – E1 (E13 – 14)	V ↔ BR	Idling	Pulse generation
KNK1 (E12 – 5) – E1 (E13 – 14)	B ↔ BR	Idling	Pulse generation (SeepageDI-47)
KNK2 (E12 – 13) – E1 (E13 – 14)	W ↔ BR	Idling	Pulse generation (SeepageDI-47)
NSW (E14 – 22) – E1 (E13 – 14)	B-W ↔ BR	IG switch ON (Other shift position in "P", "N" position)	9 ~ 14
		IG switch ON (Shift position in "P", "N" position)	0 ~ 3.0
SPD (E14 - 9) - E1 (E13 - 14)	V ↔ BR	IG switch ON (Rotate driving wheel slowly)	Pulse generation (See page DI-56)
TC (E12 – 8) – E1 (E13 – 14)	P-B ↔ BR	IG switch ON	9 ~ 14
W (E14 – 5) – E1 (E13 – 14)	W ↔ BR	Idling	9 ~ 14
		IG switch ON	Below 3.0
A/C (E14 – 10) – E1 (E13 – 14)	W-G ↔ BR	A/C switch ON	9 ~ 14
		A/C switch OFF	Below 2.0
ACT (E14 - 21) - E1 (E13 - 14)	L-B ↔ BR	Idling, A/C switch OFF	Below 2.0
		Idling, A/C switch ON	9 ~ 14
IMI (E12 – 12) – E1 (E13 – 14)	L-B ↔ BR	Idling	Pulse generation
IMO (E13 – 23) – E1 (E13 –14)	L-R ↔ BR	A few sec. after engine starting	Pulse generation