
## BOOST\_ALTITUDE COMPENSATIONAL\_STOPPER (BACS)\_SYSTEM\_(1HD-T) ON-VEHICLE\_INSPECTION

EC09D-0

1. INSPECTEGR SYSTEM (See page EC-6)



## 2. INSTALL VACUUM GAUGE

Using a 3 way connector, connect a vacuum gauge to the hose between the BACS union and high altitude compensator.

## 3. INSPECT HOT ENGINE CONDITION

- (a) Warm up the engine, the coolant temperature should be above 70°C (104°F).
- (b) When the adjusting lever of the injection pump is quickly pushed to full open, check that the vacuum gauge indicator slowly increases from 0 to 40.0 kPa (300 mmHg, 11.8 in. Hg).

If no problem is found with this inspection, system is normal; Otherwise inspect each port.

## 4. REMOVE VACUUM GAUGE