

5. Pillar Garnish

- The shapes of the pillar garnishes have been changed on the models that support the curtain shield airbags.
- Hooks for attaching a room separator only in the rear section have been provided on the models for Europe equipped with curtain shield airbags. (They are available as a set option on the models with rear three-point seat belts.)



258RV18



258RV19

6. Door Assist Grip

• The decorative portion of the surface treatment on the door assist grip has been changed from the conventional type to one with a high-quality look.

