LMI Methods in Optimal and Robust Control

Matthew M. Peet Arizona State University

Lecture 08: The Optimal Control Framework

2-input 2-output Framework



We introduce the control framework by separating internal signals from external signals.

Output Signals:

- z: Output to be controlled/minimized
 - Regulated output
- y: Output used by the controller
 - Must be measured in real-time by sensor
 - May replicate signals from regulated output

M. Peet Lecture 08: 2 / 21

2-input 2-output Framework




Input Signals:

- w: Disturbance, Tracking Signal, etc.
 - exogenous input
- u: Output from controller
 - Input to actuator
 - Not related to external input

M. Peet Lecture 08: 3 / 21

The Optimal Control Framework

The controller closes the loop from y to u.



For a linear system P, we have 4 subsystems.


$$\begin{bmatrix} z \\ y \end{bmatrix} = \begin{bmatrix} P_{11} & P_{12} \\ P_{21} & P_{22} \end{bmatrix} \begin{bmatrix} w \\ u \end{bmatrix}$$

All P_{ij} are MIMO

$$P_{11}: w \mapsto z$$
 $P_{12}: u \mapsto z$ $P_{21}: w \mapsto y$ $P_{22}: u \mapsto y$

M. Peet Lecture 08: 4 / 21

The Optimal Control Framework




Note that systems, like matrices, are also closed under **Concatenation**. That is, we can stack them horizontally or vertically.

Note also the signals move right to left. This makes it easier to read the block diagram as an equation of the form

$$LHS = RHS$$


The Regulator


First Step: Formulate the control problem in the 2-input/2-output framework.



If we define








We use a Regulator when we are trying to suppress the effect of disturbances on outputs of the system.

The Regulator



The reconfigured plant P is given by


$$\begin{bmatrix} z_1(t) \\ z_2(t) \\ y(t) \end{bmatrix} = \underbrace{\begin{bmatrix} P_0 & 0 & P_0 \\ 0 & 0 & I \\ P_0 & I & P_0 \end{bmatrix}}_{P} \begin{bmatrix} w_1(t) \\ w_2(t) \\ u(t) \end{bmatrix}$$

If $P_0 = (A, B, C, D)$, then

$$P = \begin{bmatrix} A & B & 0 & B \\ \hline C & D & 0 & D \\ 0 & 0 & 0 & I \\ C & D & I & D \end{bmatrix}$$

M. Peet Lecture 08: 6 / 21

The Regulator



Note also that getting from

$$\begin{bmatrix} P_0 & 0 & P_0 \\ 0 & 0 & I \\ P_0 & I & P_0 \end{bmatrix}$$


to


$$P = \begin{bmatrix} A & B & 0 & B \\ \hline C & D & 0 & D \\ 0 & 0 & 0 & I \\ C & D & I & D \end{bmatrix}$$

is not an algebraic operation.

If we were using *Transfer Functions*, however, we could use the algebraic representation.


Diagnostics





M. Peet Lecture 08: 7 / 21

Tracking Control




$r={ m \ tracking \ input}$	$w_2 = n_{proc}$	$w_1 = r$
e= tracking error	$w_3 = n_{sensor}$	u = u
$n_{proc} = $ process noise	$z_1 = e$	$y_1 = r$
$n_{sensor} = $ sensor noise	$z_2 = u$	$y_2 = y_p$

M. Peet Lecture 08: 8 / 21

Lecture 08

- When using the Tracing Framework we do not want the output of the nominal plant to be zero.
- Instead we want the difference between the nominal output and the reference to be zero.
- In the optimal control framework, we always want the output (z) of the enlarged plant P to be zero.

Tracking Control



$$P = \begin{bmatrix} I & -P_0 & 0 & -P_0 \\ 0 & 0 & 0 & I \\ I & 0 & 0 & 0 \\ 0 & P_0 & I & P_0 \end{bmatrix}$$

$$z_1 = r - P_0(n_{proc} + u)$$


$$z_2 = u$$

$$y_1 = r$$

$$y_2 = w_3 + P_0(n_{proc} + u)$$

M. Peet Lecture 08: 9 / 21


Lecture 08



Note the treatment of systems as algebraic objects

Linear Fractional Transformation

Close the loop



Plant:

$$\begin{bmatrix} z \\ y \end{bmatrix} = \begin{bmatrix} P_{11} & P_{12} \\ P_{21} & P_{22} \end{bmatrix} \begin{bmatrix} w \\ u \end{bmatrix} \qquad \text{where} \qquad P = \begin{bmatrix} A & B_1 & B_2 \\ \hline C_1 & D_{11} & D_{12} \\ C_2 & D_{21} & D_{22} \end{bmatrix}$$

Controller:

$$u = Ky \qquad \text{where} \qquad K = \left[\begin{array}{c|c} A_K & B_K \\ \hline C_K & D_K \end{array} \right]$$

M. Peet Lecture 08: 10 / 21

Linear Fractional Transformation

$$z = P_{11}w + P_{12}u$$
$$y = P_{21}w + P_{22}u$$
$$u = Ky$$

Solving for u,

$$u = KP_{21}w + KP_{22}u$$

Thus

$$(I - KP_{22})u = KP_{21}w$$

 $u = (I - KP_{22})^{-1}KP_{21}w$

Now we solve for z:

$$z = [P_{11} + P_{12}(I - KP_{22})^{-1}KP_{21}] w$$


M. Peet 11 / 21 Lecture 08:

Linear Fractional Transformation

This expression is called the Linear Fractional Transformation of (P,K), denoted

$$\underline{\mathsf{S}}(P,K) := P_{11} + P_{12}(I - KP_{22})^{-1}KP_{21}$$


AKA: Lower Star Product



M. Peet Lecture 08: 12 / 21


Other Fractional Transformations

Lower LFT:



$$\underline{\mathsf{S}}(P,K) := P_{11} + P_{12}(I - KP_{22})^{-1}KP_{21}$$

Upper LFT:




$$\bar{S}(P,K) := P_{22} + P_{21}Q(I - P_{11}Q)^{-1}P_{12}$$

M. Peet Lecture 08: 13 / 21

Other Fractional Transformations

Star Product:



$$S(P,K) := \begin{bmatrix} \underline{\mathsf{S}}(P,K_{11}) & P_{12}(I-K_{11}P_{22})^{-1}K_{12} \\ K_{21}(I-P_{22}K_{11})^{-1}P_{21} & \bar{S}(K,P_{22}) \end{bmatrix}$$

M. Peet Lecture 08: 14 / 21

The interconnection doesn't always make sense.

Definition 1.

The interconnection $\underline{S}(P,K)$ is **well-posed** if for any smooth w and any x(0) and $x_K(0)$, there exist functions x,x_K,u,y,z such that

$$\begin{split} \dot{x}(t) &= Ax(t) + B_1 w(t) + B_2 u(t) \\ z(t) &= C_1 x(t) + D_{11} w(t) + D_{12} u(t) \\ y(t) &= C_2 x(t) + D_{21} w(t) + D_{22} u(t) \end{split} \qquad \dot{x}_K(t) &= A_K x_K(t) + B_K y(t) \\ u(t) &= C_K x_K(t) + D_K y(t) \end{split}$$

Note: The solution does not need to be in L_2 .

• Says nothing about stability.

M. Peet Lecture 08: 15 / 21

The interconnection dense's always make sees. **Definition 3.**The interconnection S(P,K) is well-proved if for any streach v and any x(0) and $x_{K}(0)$, there exist functions $x_{K}(x,y_{1})$, such that $x(x,y_{1})$, there exist functions $x_{K}(x,y_{1})$ is which $y_{1}(x,y_{1})$ is $y_{1}(x,y_{1})$. The $y_{1}(x,y_{1})$ is $y_{2}(x,y_{1})$ in $y_{2}(x,y_{1})$ in $y_{3}(x,y_{1})$ in $y_{3}(x$

Note: The solution does not need to be in ${\cal L}_2$. • Says nothing about stability.

Well-Posedness

- State-space systems always have a solution.
- If there is a state-space representation of the closed-loop system, the interconnection is well-posed.
- If we were to use the Transfer Function representation, we would be looking at whether the closed-loop TF is rational and proper
- ullet There exists a system-level version of well-posedness, but requires us to define the extended space L_{2e} of functions integrable on finite intervals. (needed for passivity, IQCs, etc.)

In state-space format:

$$\begin{bmatrix} \dot{x}(t) \\ \dot{x}_K(t) \end{bmatrix} = \begin{bmatrix} A & 0 \\ 0 & A_K \end{bmatrix} \begin{bmatrix} x(t) \\ x_K(t) \end{bmatrix} + \begin{bmatrix} B_2 & 0 \\ 0 & B_K \end{bmatrix} \begin{bmatrix} u(t) \\ y(t) \end{bmatrix} + \begin{bmatrix} B_1 \\ 0 \end{bmatrix} w(t)$$
$$z(t) = \begin{bmatrix} C_1 & 0 \end{bmatrix} \begin{bmatrix} x(t) \\ x_K(t) \end{bmatrix} + \begin{bmatrix} D_{12} & 0 \end{bmatrix} \begin{bmatrix} u(t) \\ y(t) \end{bmatrix} + D_{11}w(t)$$

From

$$u(t) = D_K y(t) + C_K x_K(t)$$

$$y(t) = D_{22} u(t) + C_2 x(t) + D_{21} w(t),$$

we have

$$\begin{bmatrix} I & -D_K \\ -D_{22} & I \end{bmatrix} \begin{bmatrix} u(t) \\ y(t) \end{bmatrix} = \begin{bmatrix} 0 & C_K \\ C_2 & 0 \end{bmatrix} \begin{bmatrix} x(t) \\ x_K(t) \end{bmatrix} + \begin{bmatrix} 0 \\ D_{21} \end{bmatrix} w(t).$$

Because the rest is state-space, the interconnection is well-posed if and only if the matrix $\begin{bmatrix} I & -D_K \\ -D_{22} & I \end{bmatrix}$ is invertible.

M. Peet Lecture 08: 16 / 21

Question: When is

$$\begin{bmatrix} I & -D_K \\ -D_{22} & I \end{bmatrix}$$

invertible?

Answer: 2x2 matrices have a closed-form inverse

$$\begin{bmatrix} I & -D_K \\ -D_{22} & I \end{bmatrix}^{-1} = \begin{bmatrix} I + D_K Q D_{22} & D_K Q \\ Q D_{22} & Q \end{bmatrix}$$

where $Q = (I - D_{22}D_K)^{-1}$.

Proposition 1.

The interconnection $\underline{S}(P,K)$ is well-posed if and only if $(I-D_{22}D_K)$ is invertible.

- Equivalently $(I D_K D_{22})$ is invertible.
- Sufficient conditions: $D_K = 0$ or $D_{22} = 0$.
- To optimize over K, we will need to enforce this constraint somehow.

M. Peet Lecture 08: 17

S(P, K) is well-posed if and only if $(I - D_{22}D_K)$ is

- Equivalently $(I D_K D_{22})$ is invertible.
- Sufficient conditions: $D_K = 0$ or $D_{22} = 0$.
- The Simplest example of a system which is not well-posed is interconnection of matrices $D_K = I$ and $D_{22} = I$.
- This corresponds to audio feedback (Larsen Effect) when a microphone and speaker are placed next to each other.

We now have the state-space representation of $\underline{S}(P, K)$.

$$\begin{bmatrix} \dot{x}(t) \\ \dot{x}_{K}(t) \end{bmatrix} = \begin{pmatrix} \begin{bmatrix} A & 0 \\ 0 & A_{K} \end{bmatrix} + \begin{bmatrix} B_{2} & 0 \\ 0 & B_{K} \end{bmatrix} \begin{bmatrix} I & -D_{K} \\ -D_{22} & I \end{bmatrix}^{-1} \begin{bmatrix} 0 & C_{K} \\ C_{2} & 0 \end{bmatrix} \end{pmatrix} \begin{bmatrix} x(t) \\ x_{K}(t) \end{bmatrix}$$

$$+ \begin{bmatrix} B_{1} + B_{2}D_{K}QD_{21} \\ B_{K}QD_{21} \end{bmatrix} w(t)$$

$$z(t) = \begin{pmatrix} \begin{bmatrix} C_{1} & 0 \end{bmatrix} + \begin{bmatrix} D_{12} & 0 \end{bmatrix} \begin{bmatrix} I & -D_{K} \\ -D_{22} & I \end{bmatrix}^{-1} \begin{bmatrix} 0 & C_{K} \\ C_{2} & 0 \end{bmatrix} \end{pmatrix} \begin{bmatrix} x(t) \\ x_{K}(t) \end{bmatrix}$$

$$+ (D_{11} + D_{12}D_{K}QD_{21}) w(t)$$

where
$$Q = (I - D_{22}D_K)^{-1}$$

Optimal Control

Definition 2.

The Optimal H_{∞} -Control Problem is

$$\min_{K\in H_{\infty}} \lVert \underline{\mathsf{S}}(P,K) \rVert_{H_{\infty}} = \lVert \underline{\mathsf{S}}(P,K) \rVert_{\mathcal{L}(L_2)}$$

ullet Also Optimal H_{∞} dynamic-output-feedback Control Problem

Definition 3.

The **Optimal** H_2 -Control Problem is

$$\min_{K\in H_\infty} \|\underline{\mathbf{S}}(P,K)\|_{H_2} \quad \text{such that}$$

$$\underline{\mathbf{S}}(P,K)\in H_\infty.$$

M. Peet Lecture 08: 18 / 21

Optimal Control

Choose K to minimize

$$||P_{11} + P_{12}(I - KP_{22})^{-1}KP_{21}||_{H_{\infty}}$$

Equivalently choose $\left[\begin{array}{c|c} A_K & B_K \\ \hline C_K & D_K \end{array} \right]$ to minimize

$$\left\| \begin{bmatrix} \begin{bmatrix} A & 0 \\ 0 & A_K \end{bmatrix} + \begin{bmatrix} B_2 & 0 \\ 0 & B_K \end{bmatrix} \begin{bmatrix} I & -D_K \\ -D_{22} & I \end{bmatrix}^{-1} \begin{bmatrix} 0 & C_K \\ C_2 & 0 \end{bmatrix} & B_1 + B_2 D_K Q D_{21} \\ B_K Q D_{21} \end{bmatrix} \right\|_{H_{\infty}}$$

where $Q = (I - D_{22}D_K)^{-1}$.

In either case, the problem is Nonlinear.

M. Peet Lecture 08: 19 /



There are 3 ways to linearize this problem.

2022-06-07

- A change of variables and the Coprime factorization/Youla parameterization approach (Not discussed, but introduced)
- The special case of static full-state feedback (Also a change of variables).
- A change of variables in the dynamic output feedback case.

Optimal Control


There are several ways to address the problem of nonlinearity.

$$||P_{11} + P_{12}(I - KP_{22})^{-1}KP_{21}||_{H_{\infty}}$$

Variable Substitution: The easiest way to make the problem linear is by declaring a new variable $R:=(I-KP_{22})^{-1}K$

The optimization problem becomes: Choose ${\it R}$ to minimize

$$||P_{11} + P_{12}RP_{21}||_{H_{\infty}}$$



M. Peet Lecture 08: 20 / 21

Optimal Control

We optimize

$$||P_{11} + P_{12}(I - KP_{22})^{-1}KP_{21}||_{H_{\infty}} = ||P_{11} + P_{12}RP_{21}||_{H_{\infty}}$$

Once, we have the optimal R, we can recover the optimal K as

$$K = R(I + RP_{22})^{-1}$$

Problems:

- how to optimize $\|\cdot\|_{H_{\infty}}$.
- Is the controller stable?
 - ▶ Does the inverse $(I + RP_{22})^{-1}$ exist? Yes.
 - Is it a bounded linear operator?
 - In which space?
- An important branch of control.
 - Coprime factorization
 - ► Youla parameterization
- We will sidestep this body of work.

M. Peet Lecture 08: 21 / 21