B) L.

## Course Name: MANAGING WORK-AT-HEIGHTS COURSE



(Course code : CIS/(100435LS)

	\\				
Batch ID: ES-MWAH-E-293.0-2023	Exam Date/ Total Hrs	.\10/02/2023&1 Hours			
A TERRET	E CAREATI DEE AER				
Assessment Center: EXERSAFE ACADEMY PTE. LTD.					
Student\Name(As per NRIC/WP/FIN):					
SUPRAMANIYAN KUMAR					
SUPRAMANITAN KUMAR					
NRIC/FIN / WP NO: XXXXX635T	Course Dates: 08/02/	/2023 To 10/02/2023			

## Office Use Only:

(Filled by Assessor)

SL NO	ASSESSMENT DETAILS	DURATION	TOTAL	MARKS OBTAINED	PASS / FAIL
$\mathbf{A}$	MCQ (Written Test- 35 Questions)	120 Minutes	70 Marks		
В	Scenario Based Questions. Select 2 of the 5 scenarios provided (30 marks)		30 Marks	17	
	TOTAL MARKS ( PAR	T I + PART II)	100 MARKS		
SECTION A&B – PASSING MARKS IS 70%.					
II	Practical Performance	180 Minutes	C OR NYC		
			FIN	AL RESULT:	

Overall Assessment:	
The trainee has been assessed a	s (tick appropriate box):
Pass	
Fail	
	y h
	of Can Esasa
(Candidate's signature)	(Assessor's signature)
Name: supramaniyan kumar	Name: 7-SAI PRISSAD
Date: 10/02/2023	Date: 10/02/23
Feedback on the outcome by	the Assessor:
Feedback by the candidate aft	ter attending MWAH course:
Refer the attached feedback for	<u>m</u>
Note to candidates:	
	greeing to accept the assessment outcome.
Candidates may appeal against	the outcome of the assessment.

BOOKLET NO:	01
-------------	----

## ON:B (Answer any 2 Questions)

control measures

apply for pow competent ferson supervisor Contact. For R/A Briefing. For workers

4) Condact for IBM

Good Commonicade, an

6) Provide barrication/ signage -

I) Provide Wearing Proper PPE.

Safety measure Implement Kisk Assessment Conducted.


Safe work procedure impremented


PRYMIT TO WORK THAPLEMENTED. working at Trained Experienced workers

competent supervisor monitoring The work worker wearing full body harness attached

worker briefed on Safe work procedure-s,

IT is supervisor duty to brief The workers on the hazards and control measure be fore Start work start





DA Compay provide for Tower Scafford (WAH) (competent person Erection for Scafford.

Scafford Supervisor / Frector.

Scafe Acresol Point - Guard rail - Toe board.

WAH 2) apply prw. For working at leight alt
ensure prw has been endorsed and approved before
commencential commences company
28 - 20 Worker need WAH at Training Company 4) Scafford Try Folay voniet 5) Contact \_TBM-6) Briefing R/A & SWP- For WAH 7) working area Provide barricate/8/ghage 8) Provide Watcher - I Person. 9) monitoring Supervisor au times 2) (0) Wearing body harness (1) Wearing proper PPE IT IS Supervisors duty to brief the workers 36on the hazards and control measures before start work workers Restonsibility 1s to understans the hazards and control measures associated with The assigned works

MWAH-AS-09 Ver 3.00 Rev 01, 01 Apr 2018