

Course Name: MANAGING WORK-AT-HEIGHTS COURSE

(Course code: CIS/100435LS)



Batch ID: Es-MWAH-E-293.0-2023		Exam Date/ Total Hrs.: 10/02/2023&1 Hours					
Assessment Center: <u>EVERSAFE ACADEMY PTE. LTD.</u>							
Student Name(As per NRIC/WP/FIN) :							
CHOWDHURY ABU BAKAR							
NRIC/ FIN / WP NO: Course Dates: Course Dates:					33		
Office Use Only: (Filled by Assessor)							
SL NO	ASSESSMENT DETAILS	DURATION	TOTAL MARKS	MARKS OBTAINED	PASS / FAIL		
A	MCQ (Written Test- 35 Questions)	120 Minutes	70 Marks				
, n	Scenario Based Questions. Select 2 of the 5 scenarios provided (30						
В	marks)		30 Marks	17			
	TOTAL MARKS (PAR	100 MARKS					
SECTION A&B – PASSING MARKS IS 70%.							
II	Practical Performance	180 Minutes	C OR NYC	C	- /		

FINAL RESULT:

	Overall Assessment:	
	The trainee has been assessed	as (tick appropriate box):
	Pass	
	Fail	
	A	Halan
10.17	(Candidate's signature)	(Assessor's signature)
Name: _ сно	WDHURY ABU BAKAR A	Name: Y-SAI PRASAD
Date: 10/	02/2023	Date: 10/01/23
	Feedback on the outcome b	y the Assessor:
	Feedback by the candidate	after attending MWAH course:
	Refer the attached feedback for	<u>orm</u>
	Note to candidates:	
		s agreeing to accept the assessment outcome. est the outcome of the assessment.

need to write 3 Unsafe Acks

SECTION:B (Answer any 2 Questions)

@ OApply P. t. w.

- RIA SIWP bani bris
- tool box mating.
- D boom lift
 - @ pensonnel liFt
 - 3 tower seaffolds & seissons lift
- tower scaffold use the before chack the safe tae, eveny 7 day chack

The seaffold supenvigon,

- MEWP using before must be opented only by the trained person
- D supervison brief must hed to WAH courses
 - @ sexfold enoution must need to enouton
 - use only competant penson only

work before must put barreed, and singh,

in progress. Denger.

D Apply: P.F.W (4)
O D don't pert the banegate.
@ dont have the tea boots
3 valeed support don't nave
To grad Rall no have
6 man Heting.
6 o poper Aceease dont hove.
@ Saff SCAFFOLD tag don't have.
Mentin B eveny 3 mater over Accese,
Self @ madel grad neall, and top gred rall
Ho don't have
3 mon going on hating.
Oberone work must put burneed and
WORK in progress.
@ maderel put the stronge area.
B Need to bankas maning
poper Acees making Buonk after must need to house keping. MWAH-AS-09 Ver 3.00 Rev 01, 01 Apr 2018 Copyright 2018 © Eversafe Academy Pte. Ltd. All rights reserved. Page 5 of 10