

Name	Tag	RegisterType	Address	Type	Factor	Offset	Unit	Action	ScaleFactor
Stress Var 0	stress_tag_0	Discrete Input	0x9c40	STR20	1/10	34	%	RW	1
Stress Var 1		Coil	40002	I32_WB	0.1	18	A	RW	-2
Stress Var 2	stress_tag_2	Discrete Input	40004	STR20	1	58	V	R	-2
Stress Var 3		Input Register	40006	IPV6	0.1	20		R	1
Stress Var 4	stress_tag_4	Input Register	40008	U16	0.1	16	%	RW	-2
Stress Var 5		Discrete Input	40010	MAC	0.001	38	°C	R	0
Stress Var 6	stress_tag_6	Discrete Input	40012	unsigned int 16	1	12	°C	Write	0
Stress Var 7		Coil	40014	STR20	0.1	87	%	4	3
Stress Var 8	stress_tag_8	Discrete Input	40016	U64_B	0.1	51	%	Write	-2
Stress Var 9		Coil	40018	U16	1/10	6	°C	R	1
Stress Var 10	stress_tag_10	Discrete Input	40020_0_1	BITS	0.001	82	°C		3
Stress Var 11		Discrete Input	40022	unsigned int 16	1	2	A	1	-3
Stress Var 12	stress_tag_12	Discrete Input	40024	STR20	1	91	A	Write	0
Stress Var 13		Holding Register	40026	I32_WB	0.1	20	W		2
Stress Var 14	stress_tag_14	Input Register	40028	STR20	1	40	W	4	3
Stress Var 15		Coil	40,030	IPV6	0.1	23	A	1	1
Stress Var 16	stress_tag_16	Holding Register	40032	IPV6	0.001	67	°C	R	-1
Stress Var 17		Coil	40034_0_1	BITS	1	50	°C	4	0
Stress Var 18	stress_tag_18	Holding Register	40036	unsigned int 16	0.001	45	A	1	-2
Stress Var 19		Input Register	40038	I32_WB	1	2	A	R	0
Stress Var 20	stress_tag_20	Discrete Input	0x9c68	STR20	0.001	7	%	R	0
Stress Var 21		Coil	40042	STR20	0.001	32	W	4	-1
Stress Var 22	stress_tag_22	Coil	40044	I32_WB	0.001	94	A	1	3
Stress Var 23		Holding Register	40046	I32_WB	1	61		Write	1
Stress Var 24	stress_tag_24	Coil	40048	MAC	0.1	37	W	RW	1
Stress Var 25		Input Register	40050	I32_WB	0.001	39	°C		3
Stress Var 26	stress_tag_26	Input Register	40052	STR20	1	88	A	R	1
Stress Var 27		Coil	40054	unsigned int 16	0.001	99	A		3
Stress Var 28	stress_tag_28	Coil	40056	IPV6	0.1	71	A	RW	2
Stress Var 29		Holding Register	40058	U16	0.001	69	V	R	-3
Stress Var 30	stress_tag_30	Input Register	0x9c7c	IP	0.1	84	A		1
Stress Var 31		Coil	40062	F32	1/10	14	A	4	2
Stress Var 32	stress_tag_32	Input Register	40064	F32	0.001	11	A	4	1

Name	Tag	RegisterType	Address	Type	Factor	Offset	Unit	Action	ScaleFactor
Stress Var 33		Coil	40066	F32	0.001	36		R	0
Stress Var 34	stress_tag_34	Holding Register	40068	F32	0.001	78	%	RW	-2
Stress Var 35		Discrete Input	40070	IPV6	0.1	90	A	4	0
Stress Var 36	stress_tag_36	Holding Register	40072	IP	0.001	60	%	R	-3
Stress Var 37		Holding Register	40074	unsigned int 16	0.001	100	A	Write	-1
Stress Var 38	stress_tag_38	Holding Register	40076	IPV6	0.1	12	°C	Write	-1
Stress Var 39		Input Register	40078	float32 swap	1/10	66	°C	Write	-3
Stress Var 40	stress_tag_40	Holding Register	0x9c90	unsigned int 16	1/10	82	W	4	-2
Stress Var 41		Discrete Input	40082	float32 swap	0.001	76	W	RW	1
Stress Var 42	stress_tag_42	Input Register	40084_0_1	BITS	1/10	65	A	R	-3
Stress Var 43		Input Register	40086	I32_WB	1	46	W		0
Stress Var 44	stress_tag_44	Discrete Input	40088	I32_WB	0.001	15		RW	1
Stress Var 45		Coil	40,090	float32 swap	0.1	3		RW	0
Stress Var 46	stress_tag_46	Coil	40092	U64_B	1/10	14		Write	-1
Stress Var 47		Holding Register	40094	I32_WB	0.1	13	W	1	-2
Stress Var 48	stress_tag_48	Coil	40096	MAC	1	99	%		1
Stress Var 49		Holding Register	40098	unsigned int 16	0.001	92	A	Write	-1
Stress Var 50	stress_tag_50	Input Register	0x9ca4	I32_WB	0.1	68	A	4	3
Stress Var 51		Input Register	40102	IPV6	1	68	°C	RW	0
Stress Var 52	stress_tag_52	Coil	40104	MAC	0.001	2	%	4	-2
Stress Var 53		Discrete Input	40106	U16	0.1	36	W	R	1
Stress Var 54	stress_tag_54	Input Register	40108	IPV6	1/10	56	°C	1	-2
Stress Var 55		Coil	40110	U64_B	1	5	W	R	2
Stress Var 56	stress_tag_56	Discrete Input	40112	I32_WB	0.001	86	W	RW	1
Stress Var 57		Input Register	40114	U64_B	0.001	37	%	1	2
Stress Var 58	stress_tag_58	Discrete Input	40116	float32 swap	0.001	0	A	4	3
Stress Var 59		Holding Register	40118	I32_WB	1/10	74	%	RW	-1
Stress Var 60	stress_tag_60	Holding Register	0x9cb8	MAC	0.1	38	A	1	2
Stress Var 61		Coil	40122	IPV6	1/10	98	W	Write	2
Stress Var 62	stress_tag_62	Holding Register	40124	U16	1	26	°C	4	1
Stress Var 63		Input Register	40126	F32	0.1	9	%	RW	-1
Stress Var 64	stress_tag_64	Coil	40128_0_1	BITS	1	98	V	Write	-2
Stress Var 65		Discrete Input	40130	I32_WB	0.1	21		1	-2

Name	Tag	RegisterType	Address	Type	Factor	Offset	Unit	Action	ScaleFactor
Stress Var 66	stress_tag_66	Discrete Input	40132	IPV6	1/10	17	°C	Write	1
Stress Var 67		Discrete Input	40134	STR20	0.001	50	A	1	-2
Stress Var 68	stress_tag_68	Holding Register	40136	STR20	1/10	12	W	Write	0
Stress Var 69		Input Register	40138	IP	1	47	%	Write	1
Stress Var 70	stress_tag_70	Holding Register	0x9ccc	F32	0.1	5	V	1	-2
Stress Var 71		Coil	40142_0_1	BITS	0.001	84		R	3
Stress Var 72	stress_tag_72	Discrete Input	40144	MAC	0.1	62		4	-2
Stress Var 73		Input Register	40146	STR20	1	13		Write	-3
Stress Var 74	stress_tag_74	Discrete Input	40148	STR20	0.1	45	A	4	1
Stress Var 75		Holding Register	40,150	float32 swap	0.1	69	%	Write	-1
Stress Var 76	stress_tag_76	Coil	40152	float32 swap	0.001	83	W	R	2
Stress Var 77		Coil	40154	F32	1/10	39			3
Stress Var 78	stress_tag_78	Discrete Input	40156	U16	0.1	91		Write	1
Stress Var 79		Input Register	40158	F32	1	37	A	Write	3
Stress Var 80	stress_tag_80	Holding Register	0x9ce0	float32 swap	1/10	38	V	R	-3
Stress Var 81		Coil	40162	IP	0.1	21	A	1	-2
Stress Var 82	stress_tag_82	Discrete Input	40164	IPV6	0.1	89		4	-2
Stress Var 83		Discrete Input	40166	I32_WB	0.1	56		RW	-2
Stress Var 84	stress_tag_84	Discrete Input	40168_0_1	BITS	1/10	55	V		-1
Stress Var 85		Discrete Input	40170	F32	1/10	55	V	R	-2
Stress Var 86	stress_tag_86	Coil	40172	U16	1	86	V	1	1
Stress Var 87		Coil	40174	U16	0.1	61	W	R	2
Stress Var 88	stress_tag_88	Holding Register	40176	STR20	1	56	V	RW	1
Stress Var 89		Holding Register	40178	U16	1	33	V	RW	0
Stress Var 90	stress_tag_90	Discrete Input	0x9cf4	U16	0.001	13	V	RW	1
Stress Var 91		Input Register	40182	I32_WB	0.001	90	A	R	1
Stress Var 92	stress_tag_92	Input Register	40184	U16	0.001	61	W		3
Stress Var 93		Holding Register	40186	U64_B	1/10	36		Write	3
Stress Var 94	stress_tag_94	Input Register	40188	F32	1	48	V	1	3
Stress Var 95		Coil	40190	MAC	1/10	17	°C	RW	-1
Stress Var 96	stress_tag_96	Input Register	40192	F32	0.001	69	W	Write	0
Stress Var 97		Holding Register	40194	F32	1/10	69	W	Write	3
Stress Var 98	stress_tag_98	Input Register	40196	MAC	1/10	0	V	RW	1

Name	Tag	RegisterType	Address	Type	Factor	Offset	Unit	Action	ScaleFactor
Stress Var 99		Coil	40198	float32 swap	0.001	88	°C	R	1