

| Name          | Tag           | RegisterType     | Address   | Type            | Factor | Offset | Unit | Action | ScaleFactor |
|---------------|---------------|------------------|-----------|-----------------|--------|--------|------|--------|-------------|
| Stress Var 0  | stress_tag_0  | Holding Register | 0x9c40    | unsigned int 16 | 0.001  | 85     | A    | 4      | 2           |
| Stress Var 1  |               | Coil             | 40002     | U16             | 0.1    | 20     | W    | R      | 1           |
| Stress Var 2  | stress_tag_2  | Discrete Input   | 40004     | F32             | 0.001  | 53     | %    |        | -3          |
| Stress Var 3  |               | Discrete Input   | 40006     | MAC             | 1      | 71     |      | RW     | 1           |
| Stress Var 4  | stress_tag_4  | Discrete Input   | 40008     | STR20           | 0.1    | 74     | W    |        | 3           |
| Stress Var 5  |               | Discrete Input   | 40010     | F32             | 1/10   | 56     | A    | 4      | -2          |
| Stress Var 6  | stress_tag_6  | Discrete Input   | 40012     | I32_WB          | 0.001  | 25     |      | Write  | 2           |
| Stress Var 7  |               | Coil             | 40014     | U64_B           | 1/10   | 45     | °C   | Write  | -3          |
| Stress Var 8  | stress_tag_8  | Coil             | 40016     | U16             | 0.001  | 2      | %    | 1      | -2          |
| Stress Var 9  |               | Discrete Input   | 40018     | IP              | 0.1    | 27     | W    | 4      | -2          |
| Stress Var 10 | stress_tag_10 | Coil             | 0x9c54    | STR20           | 1/10   | 76     | °C   | RW     | -3          |
| Stress Var 11 |               | Discrete Input   | 40022     | IPV6            | 1      | 39     |      | 4      | 3           |
| Stress Var 12 | stress_tag_12 | Discrete Input   | 40024     | float32 swap    | 0.1    | 1      | °C   |        | 1           |
| Stress Var 13 |               | Input Register   | 40026     | float32 swap    | 0.1    | 50     | A    | R      | -3          |
| Stress Var 14 | stress_tag_14 | Coil             | 40028_0_1 | BITS            | 1/10   | 71     | °C   |        | -2          |
| Stress Var 15 |               | Discrete Input   | 40,030    | unsigned int 16 | 1/10   | 63     | °C   | Write  | -3          |
| Stress Var 16 | stress_tag_16 | Input Register   | 40032     | MAC             | 1      | 41     | %    | 1      | 2           |
| Stress Var 17 |               | Input Register   | 40034     | IPV6            | 0.001  | 6      | W    | Write  | -2          |
| Stress Var 18 | stress_tag_18 | Coil             | 40036     | float32 swap    | 0.1    | 98     | A    | RW     | 2           |
| Stress Var 19 |               | Coil             | 40038     | IP              | 1/10   | 93     | °C   | 1      | 3           |
| Stress Var 20 | stress_tag_20 | Holding Register | 0x9c68    | STR20           | 1      | 18     | W    | Write  | 3           |
| Stress Var 21 |               | Holding Register | 40042     | U64_B           | 0.001  | 61     | V    | 4      | 3           |
| Stress Var 22 | stress_tag_22 | Holding Register | 40044     | I32_WB          | 0.1    | 81     |      | Write  | -2          |
| Stress Var 23 |               | Input Register   | 40046     | U64_B           | 1/10   | 87     |      | R      | 3           |
| Stress Var 24 | stress_tag_24 | Holding Register | 40048     | F32             | 1/10   | 59     | °C   | 4      | -1          |
| Stress Var 25 |               | Coil             | 40050     | IPV6            | 1/10   | 49     | V    |        | 3           |
| Stress Var 26 | stress_tag_26 | Discrete Input   | 40052     | unsigned int 16 | 1/10   | 62     | W    | R      | -3          |
| Stress Var 27 |               | Discrete Input   | 40054     | IP              | 0.001  | 87     | %    | 4      | 3           |
| Stress Var 28 | stress_tag_28 | Discrete Input   | 40056     | U16             | 0.001  | 75     | A    |        | 1           |
| Stress Var 29 |               | Input Register   | 40058     | STR20           | 0.1    | 52     |      | RW     | 3           |
| Stress Var 30 | stress_tag_30 | Holding Register | 0x9c7c    | float32 swap    | 1      | 17     | %    | 4      | 2           |
| Stress Var 31 |               | Coil             | 40062     | IPV6            | 0.001  | 65     | °C   |        | 3           |
| Stress Var 32 | stress_tag_32 | Coil             | 40064_0_1 | BITS            | 0.1    | 21     | %    | 4      | -1          |

| Name          | Tag           | RegisterType     | Address   | Type            | Factor | Offset | Unit | Action | ScaleFactor |
|---------------|---------------|------------------|-----------|-----------------|--------|--------|------|--------|-------------|
| Stress Var 33 |               | Input Register   | 40066     | STR20           | 1/10   | 60     | A    | Write  | -2          |
| Stress Var 34 | stress_tag_34 | Holding Register | 40068     | IPV6            | 0.001  | 86     |      | RW     | -1          |
| Stress Var 35 |               | Discrete Input   | 40070     | STR20           | 0.1    | 94     | %    | Write  | -1          |
| Stress Var 36 | stress_tag_36 | Discrete Input   | 40072     | MAC             | 0.1    | 80     | °C   | R      | -2          |
| Stress Var 37 |               | Input Register   | 40074     | IP              | 0.1    | 96     |      | Write  | -1          |
| Stress Var 38 | stress_tag_38 | Holding Register | 40076_0_1 | BITS            | 0.001  | 75     | V    |        | 3           |
| Stress Var 39 |               | Discrete Input   | 40078_0_1 | BITS            | 1      | 2      | A    | 4      | -3          |
| Stress Var 40 | stress_tag_40 | Holding Register | 0x9c90    | F32             | 0.1    | 4      |      |        | -3          |
| Stress Var 41 |               | Input Register   | 40082_0_1 | BITS            | 0.1    | 4      | W    | RW     | 1           |
| Stress Var 42 | stress_tag_42 | Input Register   | 40084     | unsigned int 16 | 1/10   | 77     | °C   | 1      | 3           |
| Stress Var 43 |               | Input Register   | 40086     | IPV6            | 0.1    | 81     | %    | 4      | 0           |
| Stress Var 44 | stress_tag_44 | Discrete Input   | 40088     | IPV6            | 0.1    | 52     | W    | 4      | -1          |
| Stress Var 45 |               | Input Register   | 40,090    | U64_B           | 0.001  | 23     |      | R      | 1           |
| Stress Var 46 | stress_tag_46 | Coil             | 40092     | IPV6            | 0.001  | 43     | °C   | 4      | -1          |
| Stress Var 47 |               | Discrete Input   | 40094     | U16             | 0.001  | 0      | V    | R      | 0           |
| Stress Var 48 | stress_tag_48 | Holding Register | 40096     | IPV6            | 0.1    | 93     | A    | 1      | -3          |
| Stress Var 49 |               | Holding Register | 40098     | float32 swap    | 1      | 75     | V    | Write  | 2           |
| Stress Var 50 | stress_tag_50 | Holding Register | 0x9ca4    | U16             | 0.1    | 0      | V    | RW     | 1           |
| Stress Var 51 |               | Coil             | 40102     | U64_B           | 1/10   | 17     | V    | R      | 0           |
| Stress Var 52 | stress_tag_52 | Holding Register | 40104_0_1 | BITS            | 1/10   | 27     | %    | RW     | -3          |
| Stress Var 53 |               | Coil             | 40106_0_1 | BITS            | 1/10   | 85     | °C   | 4      | 3           |
| Stress Var 54 | stress_tag_54 | Input Register   | 40108     | U16             | 0.001  | 13     | A    | 1      | 2           |
| Stress Var 55 |               | Input Register   | 40110     | IP              | 1      | 11     |      | 4      | 1           |
| Stress Var 56 | stress_tag_56 | Holding Register | 40112     | MAC             | 0.1    | 40     |      | R      | 2           |
| Stress Var 57 |               | Coil             | 40114     | unsigned int 16 | 1/10   | 32     | °C   | Write  | -3          |
| Stress Var 58 | stress_tag_58 | Coil             | 40116     | STR20           | 0.001  | 8      |      | RW     | 3           |
| Stress Var 59 |               | Holding Register | 40118     | U16             | 1/10   | 6      |      | 4      | -3          |
| Stress Var 60 | stress_tag_60 | Coil             | 0x9cb8    | F32             | 1      | 62     |      |        | -3          |
| Stress Var 61 |               | Coil             | 40122     | IPV6            | 0.1    | 21     | %    |        | 0           |
| Stress Var 62 | stress_tag_62 | Discrete Input   | 40124     | float32 swap    | 1/10   | 24     | W    | Write  | -1          |
| Stress Var 63 |               | Discrete Input   | 40126_0_1 | BITS            | 0.001  | 2      | A    |        | 2           |
| Stress Var 64 | stress_tag_64 | Coil             | 40128     | F32             | 1/10   | 39     | W    | R      | -3          |
| Stress Var 65 |               | Input Register   | 40130     | MAC             | 0.001  | 89     |      | RW     | 2           |

| Name          | Tag           | RegisterType     | Address   | Type            | Factor | Offset | Unit | Action | ScaleFactor |
|---------------|---------------|------------------|-----------|-----------------|--------|--------|------|--------|-------------|
| Stress Var 66 | stress_tag_66 | Discrete Input   | 40132     | IP              | 1/10   | 40     | W    |        | -3          |
| Stress Var 67 |               | Discrete Input   | 40134     | I32_WB          | 1/10   | 23     | V    | Write  | 0           |
| Stress Var 68 | stress_tag_68 | Discrete Input   | 40136     | MAC             | 1/10   | 86     | A    | 4      | -1          |
| Stress Var 69 |               | Input Register   | 40138     | IPV6            | 0.001  | 54     | %    |        | 1           |
| Stress Var 70 | stress_tag_70 | Discrete Input   | 0x9ccc    | unsigned int 16 | 1      | 50     | °C   | RW     | 1           |
| Stress Var 71 |               | Coil             | 40142_0_1 | BITS            | 0.1    | 57     | °C   | R      | 2           |
| Stress Var 72 | stress_tag_72 | Input Register   | 40144     | IPV6            | 0.001  | 7      | W    | Write  | 3           |
| Stress Var 73 |               | Input Register   | 40146     | I32_WB          | 0.001  | 99     |      | 1      | 0           |
| Stress Var 74 | stress_tag_74 | Input Register   | 40148     | I32_WB          | 1/10   | 89     | %    | Write  | 1           |
| Stress Var 75 |               | Input Register   | 40,150    | IP              | 1      | 56     | A    | Write  | 0           |
| Stress Var 76 | stress_tag_76 | Input Register   | 40152     | U64_B           | 1/10   | 21     | V    | 1      | 3           |
| Stress Var 77 |               | Holding Register | 40154     | float32 swap    | 0.1    | 54     | °C   | 4      | -1          |
| Stress Var 78 | stress_tag_78 | Input Register   | 40156     | IP              | 0.001  | 69     | V    | R      | 0           |
| Stress Var 79 |               | Discrete Input   | 40158     | F32             | 0.001  | 76     | %    |        | -2          |
| Stress Var 80 | stress_tag_80 | Coil             | 0x9ce0    | I32_WB          | 0.001  | 72     | A    |        | 2           |
| Stress Var 81 |               | Holding Register | 40162     | I32_WB          | 0.1    | 94     | V    | R      | 2           |
| Stress Var 82 | stress_tag_82 | Input Register   | 40164     | I32_WB          | 0.001  | 20     | °C   |        | -3          |
| Stress Var 83 |               | Discrete Input   | 40166     | MAC             | 0.1    | 92     |      | R      | -3          |
| Stress Var 84 | stress_tag_84 | Holding Register | 40168     | MAC             | 0.1    | 72     | W    | 1      | -1          |
| Stress Var 85 |               | Holding Register | 40170     | I32_WB          | 1      | 34     | A    |        | -3          |
| Stress Var 86 | stress_tag_86 | Holding Register | 40172     | U16             | 1      | 72     |      | R      | -3          |
| Stress Var 87 |               | Coil             | 40174     | MAC             | 1/10   | 47     | %    | 4      | -3          |
| Stress Var 88 | stress_tag_88 | Discrete Input   | 40176     | IP              | 0.1    | 88     | V    | RW     | 0           |
| Stress Var 89 |               | Discrete Input   | 40178     | F32             | 1      | 38     | °C   | 4      | -2          |
| Stress Var 90 | stress_tag_90 | Coil             | 0x9cf4    | F32             | 1/10   | 43     |      |        | 2           |
| Stress Var 91 |               | Input Register   | 40182     | I32_WB          | 0.001  | 45     | °C   |        | -3          |
| Stress Var 92 | stress_tag_92 | Holding Register | 40184     | IPV6            | 1      | 88     | %    | 1      | 3           |
| Stress Var 93 |               | Coil             | 40186_0_1 | BITS            | 1/10   | 55     | V    |        | -2          |
| Stress Var 94 | stress_tag_94 | Coil             | 40188     | unsigned int 16 | 1      | 0      | W    | 1      | 3           |
| Stress Var 95 |               | Discrete Input   | 40190     | IPV6            | 0.1    | 98     | W    | 4      | 2           |
| Stress Var 96 | stress_tag_96 | Discrete Input   | 40192     | F32             | 1/10   | 25     |      | 1      | 3           |
| Stress Var 97 |               | Holding Register | 40194_0_1 | BITS            | 1/10   | 43     |      | 1      | 2           |
| Stress Var 98 | stress_tag_98 | Input Register   | 40196     | MAC             | 0.1    | 81     | %    | 4      | 3           |

| Name          | Tag | RegisterType     | Address | Type | Factor | Offset | Unit | Action | ScaleFactor |
|---------------|-----|------------------|---------|------|--------|--------|------|--------|-------------|
| Stress Var 99 |     | Holding Register | 40198   | U16  | 1      | 55     | W    | RW     | 3           |