

Name	Tag	RegisterType	Address	Type	Factor	Offset	Unit	Action	ScaleFactor
Stress Var 0	stress_tag_0	Holding Register	0x9c40	F32	1	54			2
Stress Var 1		Coil	40002	U64_B	0.001	26			-1
Stress Var 2	stress_tag_2	Input Register	40004	F32	1	91	°C	R	-3
Stress Var 3		Input Register	40006	I32_WB	0.1	17	V	RW	-1
Stress Var 4	stress_tag_4	Holding Register	40008	unsigned int 16	0.1	34	%	Write	0
Stress Var 5		Holding Register	40010	U64_B	0.001	93	°C		-1
Stress Var 6	stress_tag_6	Input Register	40012	float32 swap	0.1	3	W	1	-2
Stress Var 7		Coil	40014	float32 swap	1/10	10	%	Write	0
Stress Var 8	stress_tag_8	Discrete Input	40016	STR20	1/10	88	W	RW	-3
Stress Var 9		Holding Register	40018	IPV6	1	0	A	R	2
Stress Var 10	stress_tag_10	Coil	40020_0_1	BITS	1/10	27	A	R	1
Stress Var 11		Coil	40022	U64_B	0.001	79			-2
Stress Var 12	stress_tag_12	Input Register	40024_0_1	BITS	1	88	W	R	1
Stress Var 13		Input Register	40026	STR20	0.001	50	W	R	3
Stress Var 14	stress_tag_14	Coil	40028	IP	0.1	36	%	R	0
Stress Var 15		Holding Register	40,030	unsigned int 16	0.001	95	°C	RW	2
Stress Var 16	stress_tag_16	Coil	40032	U16	1/10	70	°C	4	-3
Stress Var 17		Discrete Input	40034	MAC	1	70	A	R	1
Stress Var 18	stress_tag_18	Input Register	40036	float32 swap	0.1	65	W	1	1
Stress Var 19		Coil	40038	IP	0.1	76		Write	-3
Stress Var 20	stress_tag_20	Input Register	0x9c68	IP	0.001	100	%	R	3
Stress Var 21		Input Register	40042	float32 swap	0.001	73	%	1	-2
Stress Var 22	stress_tag_22	Coil	40044	F32	1	55			2
Stress Var 23		Discrete Input	40046	MAC	1/10	17	%	RW	-3
Stress Var 24	stress_tag_24	Input Register	40048	IP	0.001	54	%	R	3
Stress Var 25		Discrete Input	40050	F32	0.001	61	%	Write	3
Stress Var 26	stress_tag_26	Discrete Input	40052	U64_B	1/10	47	°C		-3
Stress Var 27		Holding Register	40054	IPV6	1	49		R	-3
Stress Var 28	stress_tag_28	Holding Register	40056	F32	1/10	94	A	Write	-3
Stress Var 29		Input Register	40058	F32	1/10	99		R	-3
Stress Var 30	stress_tag_30	Coil	0x9c7c	unsigned int 16	1/10	11	A	1	2
Stress Var 31		Input Register	40062	I32_WB	1/10	47	V	RW	0
Stress Var 32	stress_tag_32	Discrete Input	40064_0_1	BITS	1/10	48		RW	-2

Name	Tag	RegisterType	Address	Type	Factor	Offset	Unit	Action	ScaleFactor
Stress Var 33		Coil	40066	IP	1/10	48	V	R	-1
Stress Var 34	stress_tag_34	Coil	40068	IPV6	0.1	54	°C	4	-1
Stress Var 35		Holding Register	40070	U64_B	0.001	16	°C		3
Stress Var 36	stress_tag_36	Holding Register	40072	F32	1/10	21	°C	R	1
Stress Var 37		Input Register	40074	IP	0.1	6	W	4	3
Stress Var 38	stress_tag_38	Coil	40076	U16	1	60	°C	4	-1
Stress Var 39		Holding Register	40078	IPV6	1	71	%	Write	-2
Stress Var 40	stress_tag_40	Input Register	0x9c90	IPV6	1/10	61	V	RW	-1
Stress Var 41		Input Register	40082	STR20	1	69	V		2
Stress Var 42	stress_tag_42	Coil	40084_0_1	BITS	1/10	39	°C	Write	3
Stress Var 43		Discrete Input	40086	IPV6	0.1	12	A	4	0
Stress Var 44	stress_tag_44	Discrete Input	40088	STR20	1	25	V	4	-3
Stress Var 45		Coil	40,090	U64_B	0.1	65		Write	2
Stress Var 46	stress_tag_46	Discrete Input	40092	F32	1/10	11	V	Write	3
Stress Var 47		Input Register	40094	U16	1	72	%	4	0
Stress Var 48	stress_tag_48	Input Register	40096	unsigned int 16	1/10	67		1	3
Stress Var 49		Discrete Input	40098	F32	0.001	92	%	RW	3
Stress Var 50	stress_tag_50	Holding Register	0x9ca4	unsigned int 16	1	67	%	R	-2
Stress Var 51		Discrete Input	40102	F32	0.1	55	A		2
Stress Var 52	stress_tag_52	Discrete Input	40104_0_1	BITS	1/10	54			1
Stress Var 53		Holding Register	40106	U16	1	16	°C		-2
Stress Var 54	stress_tag_54	Coil	40108_0_1	BITS	1	82	V		-1
Stress Var 55		Holding Register	40110	IP	0.1	50		R	3
Stress Var 56	stress_tag_56	Input Register	40112_0_1	BITS	0.001	10	%	RW	3
Stress Var 57		Holding Register	40114	F32	1/10	24	W		-1
Stress Var 58	stress_tag_58	Input Register	40116	MAC	1	40	A	1	-2
Stress Var 59		Coil	40118	I32_WB	0.001	52		RW	2
Stress Var 60	stress_tag_60	Discrete Input	40120_0_1	BITS	1	8		4	-3
Stress Var 61		Coil	40122	IP	1	78	V	4	0
Stress Var 62	stress_tag_62	Discrete Input	40124	unsigned int 16	1/10	56	%	RW	0
Stress Var 63		Input Register	40126	STR20	0.1	49		R	1
Stress Var 64	stress_tag_64	Coil	40128	I32_WB	1/10	3	°C		1
Stress Var 65		Input Register	40130	float32 swap	0.001	62	A	1	2

Name	Tag	RegisterType	Address	Type	Factor	Offset	Unit	Action	ScaleFactor
Stress Var 66	stress_tag_66	Discrete Input	40132	STR20	0.1	55	V	Write	-2
Stress Var 67		Input Register	40134	float32 swap	1/10	100	%	Write	-1
Stress Var 68	stress_tag_68	Input Register	40136_0_1	BITS	0.1	73	%	Write	-2
Stress Var 69		Coil	40138	IP	0.001	12	W	R	-3
Stress Var 70	stress_tag_70	Coil	0x9ccc	F32	0.1	1	%	Write	3
Stress Var 71		Coil	40142	float32 swap	1/10	90	%	RW	2
Stress Var 72	stress_tag_72	Holding Register	40144	STR20	0.001	20	A	Write	-1
Stress Var 73		Discrete Input	40146	U64_B	1	11	V	1	0
Stress Var 74	stress_tag_74	Discrete Input	40148	IP	0.001	57	°C	Write	-1
Stress Var 75		Coil	40,150	MAC	1	30	V	4	-1
Stress Var 76	stress_tag_76	Input Register	40152	IP	1/10	32	V	RW	1
Stress Var 77		Input Register	40154	IP	0.001	51		R	2
Stress Var 78	stress_tag_78	Discrete Input	40156	IP	1/10	82	°C	RW	-2
Stress Var 79		Holding Register	40158	float32 swap	0.1	2	V	Write	-3
Stress Var 80	stress_tag_80	Input Register	0x9ce0	MAC	1/10	45	%	RW	3
Stress Var 81		Holding Register	40162_0_1	BITS	1/10	86		1	-2
Stress Var 82	stress_tag_82	Holding Register	40164	U16	1	51		4	2
Stress Var 83		Discrete Input	40166_0_1	BITS	0.001	88	°C		3
Stress Var 84	stress_tag_84	Coil	40168	U64_B	0.1	40	A	1	-1
Stress Var 85		Holding Register	40170	F32	0.1	61	%	1	-2
Stress Var 86	stress_tag_86	Input Register	40172	F32	1	98		R	1
Stress Var 87		Coil	40174	F32	0.1	44	V	RW	3
Stress Var 88	stress_tag_88	Coil	40176	STR20	0.001	86	W	RW	-1
Stress Var 89		Input Register	40178	U64_B	1/10	15	W	R	-1
Stress Var 90	stress_tag_90	Coil	0x9cf4	float32 swap	1	9		RW	-2
Stress Var 91		Coil	40182_0_1	BITS	0.001	47		4	2
Stress Var 92	stress_tag_92	Coil	40184	STR20	1	85	°C	4	-2
Stress Var 93		Holding Register	40186	float32 swap	0.001	4	%	R	3
Stress Var 94	stress_tag_94	Input Register	40188	F32	0.1	72	V		-3
Stress Var 95		Holding Register	40190	F32	1	66	A	RW	-3
Stress Var 96	stress_tag_96	Discrete Input	40192	U64_B	1	57			2
Stress Var 97		Discrete Input	40194	U16	1/10	54	%	1	3
Stress Var 98	stress_tag_98	Input Register	40196	float32 swap	0.001	69	V		0

Name	Tag	RegisterType	Address	Type	Factor	Offset	Unit	Action	ScaleFactor
Stress Var 99		Discrete Input	40198	U64_B	0.001	15	A	4	1