

Name	Tag	RegisterType	Address	Type	Factor	Offset	Unit	Action	ScaleFactor
Stress Var 0	stress_tag_0	Holding Register	0x9c40	float32 swap	0.1	20	%	Write	-1
Stress Var 1		Discrete Input	40002	F32	0.001	55	W	4	1
Stress Var 2	stress_tag_2	Holding Register	40004	unsigned int 16	0.1	39	°C		2
Stress Var 3		Discrete Input	40006	IPV6	0.1	88	%	R	1
Stress Var 4	stress_tag_4	Input Register	40008	IPV6	0.001	0		RW	0
Stress Var 5		Coil	40010	F32	1	20	A	1	-3
Stress Var 6	stress_tag_6	Holding Register	40012	IP	1/10	38	V	Write	-2
Stress Var 7		Holding Register	40014	IP	0.001	90	°C	4	-3
Stress Var 8	stress_tag_8	Holding Register	40016	IP	1	86	A		-1
Stress Var 9		Holding Register	40018	float32 swap	0.1	67	W	R	2
Stress Var 10	stress_tag_10	Holding Register	0x9c54	STR20	0.001	93	%		0
Stress Var 11		Discrete Input	40022	IPV6	1	13	%		0
Stress Var 12	stress_tag_12	Coil	40024	U16	1/10	55	A	Write	2
Stress Var 13		Holding Register	40026	IPV6	0.001	43	A	1	-1
Stress Var 14	stress_tag_14	Input Register	40028	float32 swap	0.1	91	%	1	1
Stress Var 15		Coil	40,030	U16	1/10	22	A	Write	3
Stress Var 16	stress_tag_16	Input Register	40032	IP	1/10	45	°C	4	0
Stress Var 17		Holding Register	40034_0_1	BITS	0.1	69	W		0
Stress Var 18	stress_tag_18	Discrete Input	40036	STR20	0.1	80	%	RW	1
Stress Var 19		Discrete Input	40038	MAC	0.1	41		1	2
Stress Var 20	stress_tag_20	Input Register	40040_0_1	BITS	0.1	70	%	4	1
Stress Var 21		Discrete Input	40042	I32_WB	0.1	28			3
Stress Var 22	stress_tag_22	Input Register	40044	U64_B	1	21	V	4	2
Stress Var 23		Input Register	40046	I32_WB	0.1	16	A	RW	1
Stress Var 24	stress_tag_24	Holding Register	40048	U16	1	15	V	R	-1
Stress Var 25		Input Register	40050	U16	0.1	25	%	RW	0
Stress Var 26	stress_tag_26	Input Register	40052	F32	1	66	W	4	0
Stress Var 27		Discrete Input	40054	I32_WB	0.001	29	V	R	-3
Stress Var 28	stress_tag_28	Input Register	40056	unsigned int 16	1/10	40		4	-3
Stress Var 29		Holding Register	40058	I32_WB	0.001	26	%		1
Stress Var 30	stress_tag_30	Holding Register	0x9c7c	STR20	1	72	°C		0
Stress Var 31		Holding Register	40062	MAC	0.001	48	A	R	-3
Stress Var 32	stress_tag_32	Discrete Input	40064	F32	0.1	34			3

Name	Tag	RegisterType	Address	Type	Factor	Offset	Unit	Action	ScaleFactor
Stress Var 33		Discrete Input	40066	unsigned int 16	1/10	41	W	4	-3
Stress Var 34	stress_tag_34	Discrete Input	40068	IPV6	0.1	98			2
Stress Var 35		Coil	40070	I32_WB	1	3	A	Write	0
Stress Var 36	stress_tag_36	Discrete Input	40072	IP	0.001	73		Write	-3
Stress Var 37		Discrete Input	40074	I32_WB	1	22		R	1
Stress Var 38	stress_tag_38	Coil	40076	IPV6	1/10	44	W	4	-3
Stress Var 39		Holding Register	40078	STR20	1	7	V		-2
Stress Var 40	stress_tag_40	Coil	0x9c90	float32 swap	1	52	W	4	2
Stress Var 41		Discrete Input	40082	U16	1	10		RW	-1
Stress Var 42	stress_tag_42	Input Register	40084	F32	1	52	A	R	-2
Stress Var 43		Input Register	40086	MAC	1/10	61	°C		3
Stress Var 44	stress_tag_44	Holding Register	40088	U64_B	1	72	A	R	-3
Stress Var 45		Coil	40,090	IPV6	0.1	25	V	RW	-2
Stress Var 46	stress_tag_46	Input Register	40092	float32 swap	0.1	90		R	-1
Stress Var 47		Holding Register	40094_0_1	BITS	0.001	27	V	4	2
Stress Var 48	stress_tag_48	Coil	40096	IP	0.1	15	V		2
Stress Var 49		Holding Register	40098	U16	0.001	80		RW	0
Stress Var 50	stress_tag_50	Input Register	0x9ca4	float32 swap	1	63	A	RW	3
Stress Var 51		Input Register	40102	I32_WB	1	99	°C	RW	-3
Stress Var 52	stress_tag_52	Holding Register	40104	U16	0.1	67	°C	1	-1
Stress Var 53		Input Register	40106	MAC	1	89	V	4	1
Stress Var 54	stress_tag_54	Input Register	40108	IP	0.1	37	A	1	3
Stress Var 55		Discrete Input	40110	IPV6	1/10	27	V		-3
Stress Var 56	stress_tag_56	Coil	40112	U64_B	1	11	W		1
Stress Var 57		Holding Register	40114	IP	0.1	2	A		-3
Stress Var 58	stress_tag_58	Holding Register	40116	U64_B	0.001	66	W	RW	1
Stress Var 59		Holding Register	40118	STR20	0.1	63	%	Write	-2
Stress Var 60	stress_tag_60	Input Register	0x9cb8	U64_B	0.1	38		RW	0
Stress Var 61		Holding Register	40122	F32	0.001	30	°C	Write	-2
Stress Var 62	stress_tag_62	Holding Register	40124	U16	1/10	29		4	-1
Stress Var 63		Input Register	40126	U64_B	0.001	54	°C	4	3
Stress Var 64	stress_tag_64	Discrete Input	40128	I32_WB	1/10	2	°C		-2
Stress Var 65		Holding Register	40130	U64_B	0.001	60	V	Write	2

Name	Tag	RegisterType	Address	Type	Factor	Offset	Unit	Action	ScaleFactor
Stress Var 66	stress_tag_66	Discrete Input	40132	F32	0.001	33		RW	-3
Stress Var 67		Holding Register	40134	U16	0.1	72		RW	-3
Stress Var 68	stress_tag_68	Coil	40136_0_1	BITS	0.001	43	A	Write	-2
Stress Var 69		Input Register	40138	IPV6	0.001	59		1	3
Stress Var 70	stress_tag_70	Discrete Input	0x9ccc	IPV6	0.001	21	V		1
Stress Var 71		Coil	40142	I32_WB	0.1	43	°C		3
Stress Var 72	stress_tag_72	Coil	40144	U16	0.001	18	%	R	2
Stress Var 73		Holding Register	40146	float32 swap	0.1	11		R	0
Stress Var 74	stress_tag_74	Holding Register	40148	F32	1	41	°C		-3
Stress Var 75		Holding Register	40,150	float32 swap	0.1	1	V	R	-3
Stress Var 76	stress_tag_76	Input Register	40152	U16	1/10	43	°C	R	3
Stress Var 77		Input Register	40154	unsigned int 16	1	42	A		1
Stress Var 78	stress_tag_78	Coil	40156	F32	0.001	77	A	Write	2
Stress Var 79		Coil	40158	IP	0.001	31	A		3
Stress Var 80	stress_tag_80	Discrete Input	0x9ce0	float32 swap	1	4	%		-2
Stress Var 81		Coil	40162	U64_B	0.001	100	°C	1	-3
Stress Var 82	stress_tag_82	Holding Register	40164	unsigned int 16	0.001	49		R	3
Stress Var 83		Input Register	40166	STR20	1/10	44	A	RW	0
Stress Var 84	stress_tag_84	Coil	40168_0_1	BITS	0.1	46	W	RW	2
Stress Var 85		Coil	40170	STR20	1/10	18	%	R	-1
Stress Var 86	stress_tag_86	Coil	40172	STR20	1	18	W	Write	1
Stress Var 87		Holding Register	40174	MAC	1	60	%	1	-2
Stress Var 88	stress_tag_88	Holding Register	40176_0_1	BITS	1	19		Write	2
Stress Var 89		Coil	40178	U16	0.1	86	V	4	3
Stress Var 90	stress_tag_90	Holding Register	0x9cf4	STR20	1/10	100	W	Write	2
Stress Var 91		Input Register	40182	I32_WB	0.001	44	W	R	1
Stress Var 92	stress_tag_92	Coil	40184	U64_B	1	37	°C		0
Stress Var 93		Coil	40186	U64_B	1/10	72		R	-3
Stress Var 94	stress_tag_94	Discrete Input	40188	MAC	1	7	W	4	-3
Stress Var 95		Input Register	40190	IPV6	0.001	33	%	4	-3
Stress Var 96	stress_tag_96	Coil	40192	unsigned int 16	0.1	61	A	R	0
Stress Var 97		Input Register	40194	U64_B	1/10	43	%	Write	-1
Stress Var 98	stress_tag_98	Discrete Input	40196	U16	1/10	2	A	RW	-2

Name	Tag	RegisterType	Address	Type	Factor	Offset	Unit	Action	ScaleFactor
Stress Var 99		Coil	40198	U16	0.1	75	°C	1	-2