

Name	Tag	RegisterType	Address	Type	Factor	Offset	Unit	Action	ScaleFactor
Stress Var 0	stress_tag_0	Discrete Input	0x9c40	float32 swap	1	0	%	Write	-2
Stress Var 1		Holding Register	40002	IP	0.001	75			3
Stress Var 2	stress_tag_2	Holding Register	40004	STR20	1/10	98		R	2
Stress Var 3		Holding Register	40006	MAC	1/10	14	%		3
Stress Var 4	stress_tag_4	Input Register	40008	I32_WB	0.1	39	A	4	2
Stress Var 5		Discrete Input	40010	MAC	1	85	%	Write	-3
Stress Var 6	stress_tag_6	Holding Register	40012	IPV6	0.1	2	A	Write	2
Stress Var 7		Discrete Input	40014	F32	0.1	68	A		1
Stress Var 8	stress_tag_8	Discrete Input	40016	U64_B	0.1	22	%	1	0
Stress Var 9		Holding Register	40018	U16	1/10	98	%	RW	3
Stress Var 10	stress_tag_10	Coil	0x9c54	IPV6	1	39	%	R	2
Stress Var 11		Input Register	40022	float32 swap	1/10	6		Write	3
Stress Var 12	stress_tag_12	Discrete Input	40024	MAC	1	98	°C	Write	-3
Stress Var 13		Holding Register	40026	float32 swap	0.1	11	A		2
Stress Var 14	stress_tag_14	Holding Register	40028	I32_WB	0.001	12	%		1
Stress Var 15		Holding Register	40,030	IPV6	0.1	35	A	Write	-1
Stress Var 16	stress_tag_16	Discrete Input	40032_0_1	BITS	1/10	5	A		-3
Stress Var 17		Input Register	40034	I32_WB	1/10	31	%	RW	3
Stress Var 18	stress_tag_18	Coil	40036	float32 swap	1	13	W		-1
Stress Var 19		Coil	40038_0_1	BITS	0.1	63	°C	4	-3
Stress Var 20	stress_tag_20	Discrete Input	0x9c68	float32 swap	1/10	56	A	Write	2
Stress Var 21		Coil	40042_0_1	BITS	0.001	89	A	Write	1
Stress Var 22	stress_tag_22	Input Register	40044	IP	1	60	A	Write	3
Stress Var 23		Input Register	40046	I32_WB	1/10	51	%	RW	3
Stress Var 24	stress_tag_24	Coil	40048_0_1	BITS	1/10	100	W	Write	-2
Stress Var 25		Input Register	40050	STR20	0.001	10	V	Write	2
Stress Var 26	stress_tag_26	Coil	40052	U16	0.001	68	V		1
Stress Var 27		Holding Register	40054	F32	0.001	52	W	Write	-1
Stress Var 28	stress_tag_28	Discrete Input	40056	I32_WB	1	57	°C		-1
Stress Var 29		Discrete Input	40058	unsigned int 16	1/10	50	%	RW	0
Stress Var 30	stress_tag_30	Holding Register	40060_0_1	BITS	1	13	V		-3
Stress Var 31		Holding Register	40062	I32_WB	1/10	37	W	RW	1
Stress Var 32	stress_tag_32	Input Register	40064	I32_WB	0.001	24	V	4	1

Name	Tag	RegisterType	Address	Type	Factor	Offset	Unit	Action	ScaleFactor
Stress Var 33		Input Register	40066	U64_B	0.001	28	A	Write	0
Stress Var 34	stress_tag_34	Holding Register	40068	U16	1	92		1	1
Stress Var 35		Holding Register	40070	IPV6	0.1	48		Write	3
Stress Var 36	stress_tag_36	Discrete Input	40072	F32	0.1	71	W	Write	0
Stress Var 37		Holding Register	40074	IPV6	1	20	A	R	3
Stress Var 38	stress_tag_38	Discrete Input	40076	U64_B	1/10	58			3
Stress Var 39		Coil	40078	U64_B	1/10	98			0
Stress Var 40	stress_tag_40	Holding Register	40080_0_1	BITS	1	83	V	Write	-3
Stress Var 41		Discrete Input	40082	MAC	0.001	77		1	3
Stress Var 42	stress_tag_42	Coil	40084	IPV6	0.1	90	V	RW	-2
Stress Var 43		Holding Register	40086	unsigned int 16	1	3	%	R	-3
Stress Var 44	stress_tag_44	Coil	40088	IP	1/10	11	V		-3
Stress Var 45		Holding Register	40,090	IPV6	0.001	64	A	Write	-3
Stress Var 46	stress_tag_46	Coil	40092	float32 swap	1/10	81	A		-2
Stress Var 47		Coil	40094	U64_B	1	86	V	Write	-3
Stress Var 48	stress_tag_48	Input Register	40096	U64_B	1/10	50	°C	Write	0
Stress Var 49		Discrete Input	40098	IPV6	1/10	83	V	Write	1
Stress Var 50	stress_tag_50	Coil	0x9ca4	I32_WB	1/10	17		4	0
Stress Var 51		Holding Register	40102	U16	1/10	28	°C	Write	1
Stress Var 52	stress_tag_52	Holding Register	40104	U16	1/10	7	A	R	1
Stress Var 53		Discrete Input	40106	I32_WB	0.001	85	°C	1	-3
Stress Var 54	stress_tag_54	Input Register	40108	unsigned int 16	0.001	37		1	1
Stress Var 55		Discrete Input	40110	IP	0.1	53	V	RW	0
Stress Var 56	stress_tag_56	Input Register	40112	IPV6	1/10	85	V	RW	0
Stress Var 57		Holding Register	40114	STR20	0.1	35			-3
Stress Var 58	stress_tag_58	Input Register	40116	IP	0.1	42	%	Write	-2
Stress Var 59		Input Register	40118	IPV6	0.1	65	A	RW	3
Stress Var 60	stress_tag_60	Discrete Input	0x9cb8	F32	0.001	76	%	1	-1
Stress Var 61		Input Register	40122	U64_B	1/10	72	A	RW	-1
Stress Var 62	stress_tag_62	Holding Register	40124_0_1	BITS	0.001	68	%	1	-2
Stress Var 63		Holding Register	40126	STR20	1/10	4	W	R	3
Stress Var 64	stress_tag_64	Input Register	40128	F32	1/10	3			-2
Stress Var 65		Input Register	40130	STR20	1	96	°C	Write	0

Name	Tag	RegisterType	Address	Type	Factor	Offset	Unit	Action	ScaleFactor
Stress Var 66	stress_tag_66	Coil	40132	U16	0.1	62		4	-1
Stress Var 67		Holding Register	40134_0_1	BITS	0.001	3	A	Write	-1
Stress Var 68	stress_tag_68	Input Register	40136	MAC	0.1	86	V	Write	1
Stress Var 69		Input Register	40138	MAC	1/10	97	W	R	0
Stress Var 70	stress_tag_70	Coil	0x9ccc	F32	0.1	67	%	4	3
Stress Var 71		Coil	40142	STR20	0.1	49	%	Write	-1
Stress Var 72	stress_tag_72	Coil	40144	STR20	1/10	71	%		1
Stress Var 73		Coil	40146	I32_WB	0.001	0	A	R	1
Stress Var 74	stress_tag_74	Discrete Input	40148	STR20	1	42	W	1	2
Stress Var 75		Holding Register	40,150	STR20	1	68	A	R	-2
Stress Var 76	stress_tag_76	Coil	40152	U16	0.1	98	V	R	-2
Stress Var 77		Discrete Input	40154	U16	0.001	97		4	-3
Stress Var 78	stress_tag_78	Coil	40156	unsigned int 16	0.1	23	°C	1	2
Stress Var 79		Coil	40158	unsigned int 16	1	90	°C	1	3
Stress Var 80	stress_tag_80	Holding Register	0x9ce0	STR20	0.1	89	A	4	-1
Stress Var 81		Coil	40162	float32 swap	0.1	75	%	R	-2
Stress Var 82	stress_tag_82	Discrete Input	40164	float32 swap	0.001	29	%	RW	3
Stress Var 83		Discrete Input	40166	IPV6	0.001	49	A	Write	-2
Stress Var 84	stress_tag_84	Input Register	40168	unsigned int 16	1/10	58	°C		-3
Stress Var 85		Coil	40170	STR20	1/10	4	A	RW	0
Stress Var 86	stress_tag_86	Discrete Input	40172_0_1	BITS	1/10	16		1	2
Stress Var 87		Coil	40174	unsigned int 16	0.001	79	W	1	0
Stress Var 88	stress_tag_88	Discrete Input	40176	I32_WB	1/10	60	A	1	1
Stress Var 89		Discrete Input	40178	float32 swap	0.001	17	%	1	-3
Stress Var 90	stress_tag_90	Discrete Input	0x9cf4	unsigned int 16	0.1	23		1	0
Stress Var 91		Coil	40182	F32	1	74	A	1	2
Stress Var 92	stress_tag_92	Holding Register	40184	F32	1/10	37	W	1	-3
Stress Var 93		Holding Register	40186	U64_B	1	12	%	1	3
Stress Var 94	stress_tag_94	Discrete Input	40188	IPV6	1/10	67		1	0
Stress Var 95		Discrete Input	40190	F32	0.001	27		RW	1
Stress Var 96	stress_tag_96	Input Register	40192	unsigned int 16	1	60	W	R	-2
Stress Var 97		Discrete Input	40194	IP	1	94	V	RW	0
Stress Var 98	stress_tag_98	Holding Register	40196	unsigned int 16	1	58	V	RW	-3

Name	Tag	RegisterType	Address	Type	Factor	Offset	Unit	Action	ScaleFactor
Stress Var 99		Input Register	40198	unsigned int 16	1/10	23	A		2