

Name	Tag	RegisterType	Address	Type	Factor	Offset	Unit	Action	ScaleFactor
Stress Var 0	stress_tag_0	Input Register	0x9c40	IP	0.001	17	V	1	-1
Stress Var 1		Discrete Input	40002	U64_B	0.001	23	°C	1	2
Stress Var 2	stress_tag_2	Holding Register	40004	unsigned int 16	1	50	°C	RW	1
Stress Var 3		Holding Register	40006	U16	1/10	3	W		0
Stress Var 4	stress_tag_4	Holding Register	40008	U16	1/10	86	W	4	-2
Stress Var 5		Holding Register	40010	STR20	0.001	6	A	Write	2
Stress Var 6	stress_tag_6	Holding Register	40012	unsigned int 16	0.1	44	%	Write	2
Stress Var 7		Holding Register	40014	IPV6	0.1	93	°C	4	3
Stress Var 8	stress_tag_8	Holding Register	40016_0_1	BITS	1/10	3	V		-1
Stress Var 9		Holding Register	40018	IP	0.1	34	W	R	-1
Stress Var 10	stress_tag_10	Holding Register	0x9c54	unsigned int 16	1	49	V		2
Stress Var 11		Holding Register	40022	I32_WB	0.1	54	W	Write	3
Stress Var 12	stress_tag_12	Discrete Input	40024	U64_B	0.1	85	W	RW	3
Stress Var 13		Input Register	40026	I32_WB	0.001	21	W		-2
Stress Var 14	stress_tag_14	Input Register	40028	F32	1/10	52	A	4	-2
Stress Var 15		Holding Register	40030_0_1	BITS	1/10	16		R	1
Stress Var 16	stress_tag_16	Input Register	40032_0_1	BITS	0.1	93	V	Write	-1
Stress Var 17		Holding Register	40034	IP	0.001	87			-3
Stress Var 18	stress_tag_18	Coil	40036	F32	0.001	0	W		-3
Stress Var 19		Discrete Input	40038	IPV6	0.001	16		Write	-1
Stress Var 20	stress_tag_20	Discrete Input	0x9c68	I32_WB	1/10	67		R	-3
Stress Var 21		Holding Register	40042	I32_WB	1	62	°C	Write	0
Stress Var 22	stress_tag_22	Coil	40044	U64_B	0.1	93	W	Write	1
Stress Var 23		Discrete Input	40046	STR20	1/10	5	V	RW	1
Stress Var 24	stress_tag_24	Input Register	40048	U16	0.1	97	W	4	-2
Stress Var 25		Discrete Input	40050	STR20	0.001	83		R	3
Stress Var 26	stress_tag_26	Holding Register	40052	unsigned int 16	1/10	26	W	1	3
Stress Var 27		Coil	40054	U16	1	16			3
Stress Var 28	stress_tag_28	Coil	40056	float32 swap	1/10	64	%	R	-2
Stress Var 29		Input Register	40058	U16	0.1	30	%		1
Stress Var 30	stress_tag_30	Coil	0x9c7c	I32_WB	1/10	77	V		-2
Stress Var 31		Input Register	40062	U64_B	1	25	%	Write	1
Stress Var 32	stress_tag_32	Input Register	40064	I32_WB	0.1	97	A	RW	2

Name	Tag	RegisterType	Address	Type	Factor	Offset	Unit	Action	ScaleFactor
Stress Var 33		Discrete Input	40066	STR20	0.1	77	°C	4	-1
Stress Var 34	stress_tag_34	Holding Register	40068	MAC	1	97	V	R	3
Stress Var 35		Input Register	40070	IPV6	1/10	96	V	R	-3
Stress Var 36	stress_tag_36	Coil	40072	STR20	1	79			-2
Stress Var 37		Holding Register	40074	IP	1/10	80	V	Write	-1
Stress Var 38	stress_tag_38	Coil	40076	U64_B	1	15	%	Write	1
Stress Var 39		Discrete Input	40078	unsigned int 16	1	95		1	2
Stress Var 40	stress_tag_40	Coil	40080_0_1	BITS	0.001	85		4	2
Stress Var 41		Coil	40082	float32 swap	1	100	W	R	2
Stress Var 42	stress_tag_42	Discrete Input	40084_0_1	BITS	1	8	%	RW	3
Stress Var 43		Holding Register	40086	MAC	1/10	63	V	Write	0
Stress Var 44	stress_tag_44	Discrete Input	40088	U64_B	1	41	V	1	-3
Stress Var 45		Coil	40,090	F32	1	29	V	1	2
Stress Var 46	stress_tag_46	Input Register	40092	IP	1/10	41		Write	3
Stress Var 47		Holding Register	40094	U16	1/10	47	A		-3
Stress Var 48	stress_tag_48	Input Register	40096	MAC	0.1	56		4	2
Stress Var 49		Coil	40098	F32	0.1	20		R	1
Stress Var 50	stress_tag_50	Input Register	0x9ca4	MAC	1/10	77	A		3
Stress Var 51		Input Register	40102	U64_B	0.001	12		R	0
Stress Var 52	stress_tag_52	Holding Register	40104	U16	1	88	W	RW	2
Stress Var 53		Discrete Input	40106	U64_B	0.001	31	A	4	2
Stress Var 54	stress_tag_54	Coil	40108	MAC	1/10	9	V		-3
Stress Var 55		Discrete Input	40110	I32_WB	1/10	41	A	Write	2
Stress Var 56	stress_tag_56	Discrete Input	40112	unsigned int 16	0.1	58	%	4	1
Stress Var 57		Discrete Input	40114	IPV6	1/10	38	%	1	0
Stress Var 58	stress_tag_58	Input Register	40116	U64_B	1/10	5		1	3
Stress Var 59		Input Register	40118	float32 swap	0.1	45	W		3
Stress Var 60	stress_tag_60	Input Register	0x9cb8	U64_B	1	48		R	2
Stress Var 61		Holding Register	40122	unsigned int 16	0.001	36		R	-2
Stress Var 62	stress_tag_62	Holding Register	40124	STR20	0.1	4		Write	-2
Stress Var 63		Discrete Input	40126	F32	1	9	V	1	0
Stress Var 64	stress_tag_64	Input Register	40128	MAC	1	97	°C	1	3
Stress Var 65		Coil	40130	STR20	0.001	72	%	1	-2

Name	Tag	RegisterType	Address	Type	Factor	Offset	Unit	Action	ScaleFactor
Stress Var 66	stress_tag_66	Holding Register	40132_0_1	BITS	1/10	51		4	3
Stress Var 67		Input Register	40134_0_1	BITS	0.001	80	%	4	3
Stress Var 68	stress_tag_68	Holding Register	40136	F32	1	83	W	Write	-2
Stress Var 69		Holding Register	40138	unsigned int 16	0.001	26	%	R	-1
Stress Var 70	stress_tag_70	Discrete Input	0x9ccc	MAC	0.001	41	°C	1	2
Stress Var 71		Holding Register	40142	IP	0.001	38	A	4	1
Stress Var 72	stress_tag_72	Discrete Input	40144	float32 swap	1	22	W	4	3
Stress Var 73		Coil	40146	float32 swap	0.1	62	%	R	2
Stress Var 74	stress_tag_74	Coil	40148	float32 swap	1/10	76	%	RW	2
Stress Var 75		Discrete Input	40,150	U16	0.001	49	A	R	3
Stress Var 76	stress_tag_76	Discrete Input	40152	float32 swap	0.001	49		Write	-3
Stress Var 77		Input Register	40154	float32 swap	0.1	6	%	1	1
Stress Var 78	stress_tag_78	Coil	40156	U64_B	0.1	56	°C	Write	3
Stress Var 79		Discrete Input	40158_0_1	BITS	1	34	W	R	2
Stress Var 80	stress_tag_80	Holding Register	0x9ce0	U16	0.001	0	%	RW	3
Stress Var 81		Holding Register	40162	U16	1	31	A	RW	2
Stress Var 82	stress_tag_82	Holding Register	40164	U64_B	0.001	74	V	R	3
Stress Var 83		Input Register	40166	MAC	1/10	95	%	1	-2
Stress Var 84	stress_tag_84	Coil	40168_0_1	BITS	1	33	°C	Write	3
Stress Var 85		Discrete Input	40170	I32_WB	1	46	°C	4	2
Stress Var 86	stress_tag_86	Discrete Input	40172	U16	0.1	42	°C	RW	-2
Stress Var 87		Coil	40174	U64_B	0.1	48	A		3
Stress Var 88	stress_tag_88	Input Register	40176	I32_WB	0.001	31	°C	RW	-2
Stress Var 89		Input Register	40178	IPV6	1	65		Write	-1
Stress Var 90	stress_tag_90	Coil	0x9cf4	MAC	0.1	37	V		2
Stress Var 91		Coil	40182	MAC	1/10	47	°C	Write	3
Stress Var 92	stress_tag_92	Coil	40184	U64_B	1	15	%	1	3
Stress Var 93		Holding Register	40186	U64_B	1/10	93	%	R	-3
Stress Var 94	stress_tag_94	Discrete Input	40188	F32	1	20	A		-3
Stress Var 95		Coil	40190	unsigned int 16	1	74	A	R	3
Stress Var 96	stress_tag_96	Coil	40192	float32 swap	1	80	W	4	0
Stress Var 97		Discrete Input	40194	IPV6	1	21	A	1	2
Stress Var 98	stress_tag_98	Holding Register	40196	MAC	0.001	98	%		1

Name	Tag	RegisterType	Address	Type	Factor	Offset	Unit	Action	ScaleFactor
Stress Var 99		Input Register	40198_0_1	BITS	1	84		Write	1