

4810 Industrial Loop · Austin, TX 78744 · (512) 555-0147 · TACLB#42117C

Work performed under HVAC Reserve disbursement request submitted to Lakeside Commercial Lending, LLC. Two competing bids obtained per reserve account requirements (see attached bid comparison from Centerline Mechanical Services, Inc. and Hill Country Air Systems, LLC). Failed unit (RTU-4, S/N CTX-8800) removed and disposed of per EPA refrigerant recovery requirements. Before/after photographs provided separately.