


Installation Monitoring Report

Project	NW 2050 Cypress Point	Job Number	24064	RGC Number	53216
Address	7511, 7531, 7651 Minoru Boulevard	Inspector	Matthew	Report Number	36
	Richmond, B.C.	Weather	Sun / 24°C	Time	12:40pm
Contractor	Flynn Canada Ltd.	Crew Size	4 Red Seal	1 Appren	tices 1

Date: August 20, 2025

Distribution List: keith.lodge@flynncompanies.com, ken.brown@flynncompanies.com, nw2050@telus.net. matt@phoenixroofconsultants.ca



36.1 **Building A**

Cap flashing installation continues on the upper parapet walls of the main roof area.



36.2 **Building A**

Installation of the 24ga parapet and counter flashing is nearly completed on the noted Northeast deck area.




36.3 **Building A**

Cross broken panels are installed with Slock details at joints and corners.



36.4 **Building A**

Double gum lip counter flashing has finished being secured along the base of the wall, final sealant application remains.



36.5 **Building A**

The sill flashing at the base of the door details appear acceptable, the use of stainless steel rivet to secure the outside edge is acceptable.



36.6 Building A

Counter flashing application to the base of the skylight completed in an acceptable manner.



Outstanding Items:

• Items #34.6 - 34.8

Reported by:

Matthew Blackstock, RRO Phoenix Roof Consultants

Phoenix Roof Consultants field reviews are for general conformance to specifications and roofing compliance only. Our reviews are not to take the place of the contractor's own quality control which shall remain the responsibility of the contractor. Phoenix Roof Consultants will not be responsible for acts or omissions of the contractor or for the contractor's failure to fulfill the intent of the specifications, contract, or quote.