


Installation Monitoring Report

Project	NW 2050 Cypress Point	Job Number	24064	RGC Number		53216	
Address	7511, 7531, 7651 Minoru Boulevard	Inspector	Matthew	Report Number		42	
	Richmond, B.C.	Weather	Sun / 23°C	Time		12:30pm	
Contractor	Flynn Canada Ltd.	Crew Size	3 Red Seal	2	Apprent	ices	1

Date: September 8, 2025

Distribution List: keith.lodge@flynncompanies.com, ken.brown@flynncompanies.com, nw2050@telus.net. matt@phoenixroofconsultants.ca



42.1 **Building A**

Crews continue to work on various flashing details on the roof area.



42.2 **Building A**

Counter flashing application is under way around the skylights.



42.3 **Building A**

Cap flashing and downpipe reinstall with splash pad completed at elevation shaft roof.



42.4 **Building A**

Visible membrane from behind flashing to be trimmed back.



42.5 **Building A**

A lower profile debris screen fitted to the Northwest deck for review.



Outstanding Items:

• Items #34.6 – 34.8, #39.7, #40.5 - 40.13

Reported by:

Matthew Blackstock, RRO Phoenix Roof Consultants

Phoenix Roof Consultants field reviews are for general conformance to specifications and roofing compliance only. Our reviews are not to take the place of the contractor's own quality control which shall remain the responsibility of the contractor. Phoenix Roof Consultants will not be responsible for acts or omissions of the contractor or for the contractor's failure to fulfill the intent of the specifications, contract, or quote.