




AMPHR

Asset Measurement Platform Health Recorder

Building health, inspection and compliance for Dubai.

Product presentation · iPhone, iPad and laptop

powered by
MHS+

WHY AMPHR

Dubai now requires proof that buildings are safe

- **Law No. 3 of 2026** makes periodic inspection by a Dubai Municipality accredited engineering firm a legal duty for every building in Dubai, including free zones.
- **Certificates expire:** 10 years, or 5 years once the Completion Certificate is 40 years old or more.
- **Penalties:** fines of AED 100 to 1,000,000, doubled to AED 2,000,000 on repeat. Permits, land transactions and lease certification can be suspended.
- **Owners, contractors and engineering offices** have one year from the effective date to comply.

10 / 5

year certificate validity

AED 2M

maximum repeat fine

1 year

transition window

WHAT AMPHR IS

One platform from the field reading to the consultant pack

1 Capture

Spots with photos, readings and GPS-ready location on iPhone

2 Measure

Probe and instrument readings tied to calibrated equipment

3 Assess

Rule-based severity, health score and acceptance criteria

4 Prove

Certificates, calibrations and audit trail

5 Report

Consultant-ready packs for submission to Dubai BPS

Severity suggestions are rule-based, not AI. Every grade is confirmed by a named engineer.

PORTFOLIO



Portfolio health at a glance



- **Health score** = structural 40% + compliance 30% + maintenance 20% + safety 10%.
- **Bands:** green 80–100, yellow 60–79, orange 40–59, red 0–39.
- **Sample portfolio:** Heritage Tower 38, Downtown Hub 47, Marina Plaza 53, Tower Two 66, Tower One 83. Average 57.
- **Search and filter** by status and area.

SPOTS


Spots: capture a defect in the field



- **Photos, element, category and repair guidance** on every spot.
- **Readings added from probes**, interpreted against editable acceptance criteria.

FLOOR PLAN



Floor plans with defects pinned



- **Defect pins** by severity on each level.
- **GPR overlay** for rebar and objects.
- **Tap a pin** to open the spot and its readings.
- **Runs on iPad** without horizontal scrolling.

EQUIPMENT

Equipment, probes, calibrations and certificates



- **Instrument registry** for Proceq, Pundit, Profometer, Resipod, Schmidt and more, with probes and serials.
- **Calibration status** valid, due or expired, with certificate attachments.

INSPECT

Inspections: PDF upload, field checklist, manual entry

AMPHR

Asset Health Recorder

Portfolio

Spots

Floor plan

Equipment

Inspect

Compliance

Reports

Assets

Settings

Demo build: sample data is stored only in this browser. Don't enter confidential client data.

Inspect

PDFs in. Insights out.

Upload PDF

Field checklist

Manual entry

01

Inspection Checklist

02

Annotate & Assess

03

Review & Submit

Inspection Checklist

0/11 checked

BUILDING

Heritage Tower

FOUNDATION & STRUCTURAL

0/4

☐ Cracks in walls

☐ Spalling concrete

☐ Settlement

☐ Structural deformation

MEP SYSTEMS

0/4

☐ Electrical systems

☐ Plumbing systems

☐ HVAC systems

☐ Fire protection

SAFETY & ACCESS

0/3

☐ Access & egress

☐ Guardrails & barriers

AMPHR

Asset Health Recorder

Portfolio

Spots

Floor plan

Equipment

Inspect

Compliance

Reports

Assets

Settings

Demo build: sample data is stored only in this browser. Don't enter confidential client data.

Inspect

PDFs in. Insights out.

Upload PDF

Field checklist

Manual entry

Heritage_Tower_Structural_Inspection.pdf (sample)

Drop another file to replace it

Use sample report

The PDF is read in your browser. Nothing is uploaded to a server.

Parsed Information

INSPECTION DATE

10/04/2026

INSPECTOR NAME

Ahmed Hassan

REPORT TITLE

Heritage Tower – Structural Inspection

BUILDING

Heritage Tower

NEXT DUE

10/04/2027

Detected Issues

Concrete spalling on Column C4

Critical

×

Corrosion on rebar – Level 12

High

×

+ Add issue

AMPHR · Asset Measurement Platform Health Recorder · Demo build: sample data

COMPLIANCE

Law 3/2026 compliance tracker


AMPHR
 Asset Health Recorder

Portfolio
 Spots
 Floor plan
 Equipment
 Inspect
Compliance
 Reports
 Assets
 Settings

powered by
MHS+

• Demo build: sample data is stored only in this browser. Don't enter confidential client data.

Law 3/2026 Compliance Tracker

Deadlines colour-coded by urgency · alerts at 30, 14 and 1 day

COMPLIANCE TIMELINE

BUILDING	TIME TO DEADLINE >180 DAYS 90-180 DAYS <90 DAYS	ALERTS 30 D 14 D 1 D
Heritage Tower	12 days overdue · 2026-09-22 · Non-compliant	● ● ●
Downtown Hub	20 days left · 2026-10-24 · Non-compliant	● ● ●
Marina Plaza	38 days left · 2026-11-11 · Non-compliant	● ● ●
Tower Two	120 days left · 2027-02-01 · Due soon	● ● ●
Tower One	210 days left · 2027-05-02 · Compliant	● ● ●

Generate DM compliance report

AUDIT TRAIL

ACTION	TIME
Deadline updated Downtown Hub	Today, 09:42
Alert threshold set Marina Plaza	Today, 09:15
Document uploaded Heritage Tower	Today, 08:51
Status changed Downtown Hub	Yesterday, 17:03
Reminder sent Heritage Tower	Yesterday, 12:28
Deadline updated Tower Two	Yesterday, 09:41
Document uploaded Tower One	Yesterday, 08:12
Status changed Marina Plaza	2 days ago, 16:33

Tap a building to update its deadline or status.

- **Deadlines** colour-coded by urgency.
- **Alerts** at 30, 14 and 1 day.
- **Audit trail** of every status change and report.
- **DM compliance report** generated for the consultant.

DUBAI MUNICIPALITY

DM Permit Pack: structural modification readiness


AMPHR
 Asset Health Recorder

Portfolio
 Spots
 Floor plan
 Equipment
 Inspect
 Compliance
DM Permit
 Reports
 Assets
 Settings

Demo build: sample data is stored only in this browser. Don't enter confidential client data.

DM Permit Pack

Dubai Municipality structural modification: NDT scope, report contents and deliverables

Generate DM permit pack

BUILDING

Heritage Tower

REGISTRATION CATEGORY (HEIGHT)

Select

MODIFICATION TYPE

Slab penetrations / trenching

Vertical extension / mezzanine

Member retrofitting / strengthening

Post-tensioned (PT) slabs

Slab penetrations / trenching MEP risers, staircases, escalators

- GPR scanning (high frequency)
- Cover meter / Ferrosan

Objective: Map top and bottom rebar, verify bar spacing, and avoid severing post-tensioning (PT) tendons or critical shear links.

1 · MANDATORY NDT SCOPE FOR THIS MODIFICATION

☐ **GPR measurement readings recorded**
 No readings yet. Add them in Spots.

Missing

☒ **Rebar cover readings recorded**
 1 reading in Spots

Auto

2 · LABORATORY AND EQUIPMENT ACCREDITATION

☐ **Valid EIAC / ISO 17025 laboratory certificate**
 Add under Equipment > Certificates

Missing

SUBMISSION READINESS

24%

4 of 17 requirements met for Heritage Tower. Auto items read your Spots, Equipment and Certificates. Tap manual items to mark them complete.

Rules applied: testing by an EIAC-accredited / DM-registered lab, submitted via BPS by a DM-licensed consultant. Core sampling to BS EN 12504-1 / ASTM C42. Technical approval for non-standard systems sits with DCLD-CQPS.

- **Four modification types:** slab openings, vertical extension, retrofit, post-tensioned slabs, each with its required NDT scope.
- **Seven-section checklist** from the DM report contents, with a readiness percentage per building.


AMPHR
 Asset Health Recorder

Portfolio
 Spots
 Floor plan
 Equipment
 Inspect
 Compliance
DM Permit
 Reports
 Assets
 Settings

Demo build: sample data is stored only in this browser. Don't enter confidential client data.

DM Permit Pack

Dubai Municipality structural modification: NDT scope, report contents and deliverables

Generate DM permit pack

BUILDING

Heritage Towe

REGISTRATION CATEGORY (HEIGHT)

Select

MODIFICATION TYPE

Slab penetrations / trenching

Vertical extensi

Slab penetrations / trenching MEP risers, staircases, escalators

- GPR scanning (high frequency)
- Cover meter / Ferrosan

Objective: Map top and bottom rebar, verify bar spacing, and avoid severing post-tensioning (PT) tendons or critical shear links.

1 · MANDATORY NDT SCOPE FOR THIS MODIFICATION

☐ **GPR measurement readings recorded**
 No readings yet. Add them in Spots.

Missing

☒ **Rebar cover readings recorded**
 1 reading in Spots

Auto

2 · LABORATORY AND EQUIPMENT ACCREDITATION

☐ **Valid EIAC / ISO 17025 laboratory certificate**
 Add under Equipment > Certificates

Missing

SUBMISSION READINESS

24%

4 of 17 requirements met for Heritage Tower. Auto items read your Spots, Equipment and Certificates. Tap manual items to mark them complete.

Rules applied: testing by an EIAC-accredited / DM-registered lab, submitted via BPS by a DM-licensed consultant. Core sampling to BS EN 12504-1 / ASTM C42. Technical approval for non-standard systems sits with DCLD-CQPS.

REGULATORY POSITION

How AMPHR fits Dubai Municipality submission

- **No software vendor** holds DM certification or authority to file reports or issue certificates.
- **Single gateway:** Dubai BPS / Build in Dubai, used by DM-registered consultants with UAE Pass.
- **Test reports** come from EIAC-accredited labs registered with Dubai Central Laboratory.
- **AMPHR prepares** the evidence and a consultant-ready pack. The consultant reviews, signs and submits.

Field capture
AMPHR

EIAC lab
testing

DM-registered
consultant

Dubai BPS
Build in Dubai

AMPHR never claims DM certification or direct filing.

REPORTS

Reports ready for the consultant

 AMPHR
Asset Health Recorder

Portfolio

Spots

Floor plan

Equipment

Inspect

Compliance

Reports

Assets

Settings

Demo build: sample data is stored only in this browser. Don't enter confidential client data.

Reports

Compile the condition assessment report from the record

Condition assessment report

BUILDING

Heritage Tower

INCLUDE

☒ Photos with callouts

☒ Instrument data tables

☒ Equipment, calibration and certificates

SIGNING ENGINEER

Ahmed Hassan

LICENCE / REGISTRATION NO.

DM-ENG-48213 (sample)

☐ I have reviewed the findings and confirm the report is accurate and complete

Generate report

The report opens in a new tab. Use Print and choose Save as PDF.

Pre-flight checks · Heritage Tower

All spot grades are confirmed.

2 readings were taken with an instrument that had no valid calibration. They will be flagged.

Calibration expired or missing now: Profometer PM8500.

8 spots have no photograph.

8 spots and 7 readings included.

Export spots CSV

Export readings CSV

Law 3/2026 compliance report

The Dubai Municipality deadline summary and audit trail lives in the compliance tracker.

Open compliance tracker

- **Printable report** with readings, photos and grades.
- **Backup and restore** from Settings.
- **Signing engineer** and licence shown on the report.

AMPHR · Asset Measurement Platform Health Recorder · Demo build: sample data

DEVICES

One app on iPhone, iPad and laptop



Installable web app today. Offline capture on site, syncing when back online.

NEXT STEPS

Roadmap: from demo to live product

Now

Live demo at amphr-mvp.vercel.app, data in the browser only

Stage 1

Own domain, login, shared database and file storage (about 1–2 weeks)


Stage 2

iPad, iPhone and Android apps for the App Store and Google Play (about 2–3 weeks)

Stage 3

Real client data hardening: audit, backups, privacy policy, security review

Domain: mhsplus.com is already registered, so use app.mhsplus.com if MHS+ owns it, or buy a new name such as amphr.app.



See it live

amphr-mvp.vercel.app

Open on iPhone, iPad or any laptop browser.

Demo build with sample data. Reports are for engineer review and consultant submission,
not a Dubai Municipality filing.

powered by
MHS+