





ASSEMBLY INSTRUCTION NC*FXX & NC*MXX | XLR Cable Connector









- (A) Slide the boot onto the cable.
- B Prepare cable as shown.
- © Insert wires into the terminals and solder them.
- D Put chuck onto the cable.
 Attention: Pay attention to the guiding key.
- © Slide insert and chuck together into the housing.
- Finish the installation by turning the bushing onto the connector.

ORDER OF ASSEMBLY			
NC*FXX			
bushing	chuck	insert	housing
NC*MXX			STREAMED

NEUTRIK AG NEUTRIK Zürich AG NEUTRIK USA Inc. NEUTRIK (UK) Ltd.

LI CH USA UK T: +423/237 24 24 F: +423/232 53 93
T: +41 44/736 5010 F: +41 44/736 5011
T: +1732/901 9488 F: +1732/901 9608

NEUTRIK Vertriebs GmbH DE, NEUTRIK France FR NEUTRIK Tokyo Ltd. JP NEUTRIK Hong Kong Ltd. HK

H DE/NL/AT

T: +49 8131/280 890 F: +49 8131/280 830 T: +33 1/4131 6750 F: +33 1/4131 0511 T: +81 3/3663 4733 F: +81 3/3663 4796 T: +852/2687 6055 F: +852/2687 6052

NEUTRIK (UK) Ltd. UK T: +44 1983/811 441 F: +44 1983/811 439 NEUTRIK Hong Kong Ltd. HK

Draft. Nr.: BDA 158 / 3102M1381 | Update: 12..03.2008 | Data subject to change without prior notice. @2008NEUTRIK* .ALL RIGHTS RESERVED.

