

1. Title

HIMA Automated Prooftest Reporting Solution

Automatic proof-test records and reports from your station

Version 1.77 · 2026-08-20 · For operations & engineering (non-IT overview)

2. The problem

Proof tests happen in plant / SILworX. Results are easy to lose and hard to show auditors. Manual copy/paste is slow and error-prone.

3. The solution

When a proof test finishes, the tool automatically saves the results and creates the report.

Must run on the same Windows PC as the OPC / X-OPC live data link.

4. Does / Does not

Does: watch devices, detect start/end, save database, create HTML/PDF, local screen.

Does not: run the HART test, replace SILworX, close the engineer project on Disconnect, quit SILworX.


5. Who uses it

Operator/engineer — devices, Connect, reports. Maintenance/safety — history and PDFs. IT (optional) — install on station PC next to OPC.

6. Architecture

See diagram on next page / embedded below.

Architecture — who talks to whom



Caption: Live values always come from OPC. SILworX only helps identify devices when the tool is connected.


7. Station layout

One Windows station PC: SILworX, X-OPC, this tool, browser UI, reports + database.

8. End-to-end flow

See flow diagram. Optional Disconnect branch keeps OPC watching; SILworX stays open.

End-to-end flow — from test to report



9. Connect vs Disconnect

Connect links this tool only. Disconnect unlinks this tool only — never closes the project or quits SILworX.

Connect vs Disconnect — what it really means

CONNECT

- Links THIS reporting tool to SILworX
- Reads which devices exist and their types
- Does not take over SILworX
- Does not open/close the engineer's project

DISCONNECT

- Unlinks THIS tool only
- Does NOT close the engineer's project
- Does NOT quit SILworX
- Proof-test watching continues via OPC

Think of Connect/Disconnect as plugging or unplugging this tool — not turning SILworX on or off.

10. Screen

Local <http://127.0.0.1:8080>. Columns: Device, Type, OPC, Project, OPC server. Badge = tool attached, not “SILworX is running”.

11. Reports

Folder under C:\HIMA Prooftest Reporting Tool\... HTML for viewing, PDF for archive. Database keeps history.

12. Trust

Does not change PLC/SILworX test logic. Records what OPC published. Local-only screen by default.

13. Typical day

Open SILworX → Connect in tool → run tests → reports appear → optional Disconnect.

14. Benefits

Less paperwork, consistent records, faster audits, clear list when the same tag exists in two projects.

15. FAQ

Does not run the test. SILworX connect not always required. Disconnect does not stop tests. Open on local browser / desktop shortcut.

16. Close

Version 1.77. Questions: [project owner]. See OPERATOR-CONNECT-DISCONNECT.md.

Source PowerPoint

HIMA-Prooftest-Reporting-Solution-Overview.pptx