



Negative Couple Persists After Command Removal and Survives Numerical Controls


Same-State Zero-Command Geometry Controls



Shaft Deflection Remains Dynamic After the Cut



Work-Energy Residual Decreases with Timestep



Baseline Modal Storage Before the Intervention

