



No Cross-Engine Failure Was Observed Through the Registered 50 ms Horizon


Complete-Gate Pass Fraction



Worst Club-Position Difference



Worst Contact-Wrench Difference



Worst Work-Energy Closure Residual

