


Identifiability Is Tested Before Individual-Hand or Parameter Fitting

Twelve Parameters Cannot Be Identified From Six Summaries



Net Planar Wrench Leaves One Force Nullspace Mode

