



A Proper 3-D Frame Rotation Changes Components, Not Wrench Power


Frame 1: 0°




Frame 2: 25°




Frame 3: 50°



Frame 4: 76°



Frame 5: 101°



Frame 6: 126°

