















SURFACE

- 1. The first layer is broken up by explosives,
- 2. it is removed by draglines.
- 3. The coal is drilled,
- 4. fractured
- 5. and mined in strips.
- 6. It is loaded on to trucks.





UNDERGROUND MINING

TWO MAIN METHODS: