

PRE FLIGHT FLOWS

FLIGHTPLAN	FILED
WEATHER C FORECAST	CHECKED
ZFW/CG	DETERMINE
REQUEST DE-ICING (if required)	[20min EOBT]

CHOCKS	REMOVED
DOORS	CHECK CLOSED, ARMED (SLIDES)
PAX SIGNS	SET
CALCULATE T.O PERF s INIT IN MCDU	

PRELIM COCKPIT PREP

GEAR PINS C COVERS	REMOVED
PARKING BRAKE (C CHOCKS)	SET
COCKPIT DOOR	UNLOCKED/OPEN
FLAPS	UP
SPOILER	RETRACTED
ENGINE MODE SELECTOR	NORM
ENGINE MASTER SWITCHES	OFF
THROTTLE	TRUST LEVERS IDLE
WHEATHER RADAR	OFF
LANDING GEAR LEVER	CHECK DOWN
BATTERIES	VOLTAGE CHECK
GPU CONNECTED	EXT PWR AVAIL

STARTUP

BEACON LIGHT	ON
APU (FIRE TEST)	START
APU BLEED	RUN
GPU (EXT PWR OFF)	DISCONNECTED
Request Pushback- Thereafter Initiate	
THROTTLE (FIRE TEST)	THRUST LEVERS IDLE
FUEL PUMP SWITCHES	ON
ENGINE AREA	CLEAR
ENGINE MODE SELECTOR	IGN/START
ANNOUNCE LEFT ENGINE/ENG 1	
ENGINE 1	START
ANNOUNCE RIGHT ENGINE/ENG 2	
ENGINE 2	START
APU BLEED C APU	OFF
ENGINE MODE SELECTOR	NORM

PRE START

BATTERIES	ON
EXT POWER	ON
NAV C WING LIGHTS	ON
CLOCK	CHECK CORRECT TIME
CREW OX SUPPLY	ON
GND CTL (CVR TEST)	ON
ADIRS	NAV
LOAD PAX, CARGO/BAGS s FUEL	
COCKPIT DOOR	CLOSED/NORM
FUEL QUANTITY	_____KG/LB
PANEL DISPLAYS C LIGHTS	SET
Check ATIS (set altimeter)	
MCDU	SETUP
Request Enroute Clearance (5min before EOBT)	
TRANSPONDER	SET, XPNDR, TCAS ABOVE
DEPATURE BRIEFING C BOARDING	COMPLETE

AFTER START

PROBE/WINDOW HEAT	AUTO
AUTOPILOT	SET
AUTOBRAKE	MAX
GND SPOILER	ARMED
FLAPS	___SET
ANTI ICE	_____
ECAM STATUS	CHECKED
PITCH TRIM	_____%
RUDDER TRIM	NEUTRAL
FLIGHT CONTROLS	FREE & CORRECT
Request Taxi	

TAXI

TAXI LIGHTS ON
LANDING LIGHTS OFF
RWY TURN OFF LIGHTS ON
STROBE AUTO
PARKING BRAKE RELEASED
T.O RWY CONF ____
WEATHER RADAR ON
ECAM MEMO T.O NO BLUE

LINEUP

TRANSPONDER TA/RA
T.O LIGHT ON
LANDING LIGHTS ON
STROBE ON
PARKING BRAKE RELEASED
CLOCK TIMER START

CLIMB-OUT

POSITIVE RATE OF CLIMB GEAR UP
THRUST CLIMB
PASSING S SPEED FLAPS UP
AUTOPILOT ENGAGE
SPOILER RETRACTED
PASSING TA ALTIMETER STD (1013hPa)
PASSING 10'000ft LANDING LIGHTS RETRACTED
PASSING 10'000ft NOSE LIGHTS OFF
PASSING 10'000ft RWY TURN OFF LIGHTS OFF
PASSING 10'000ft SEAT BELT SIGNS OFF

CRUISE

TCAS BELOW
ARRIVAL INFORMATION (ATIS) CHECK
ARRIVAL INFORMATION (LDG PERF) MCDU
ARRIVAL ROUTE (e.g. STAR) SET MCDU
PASSING 10'000ft UNDO CLIMB-OUT CHECKLIST
ANTI ICE
PASSING TL SET ALTIMETER

APPROACH

LANDING LIGHTS CHECK ON
TAXI LIGHTS CHECK ON
GND SPOILERS ARMED
AUTO BRAKE SET
AT 6 DME GEAR DOWN
SPEED FINAL APPROACH SPEED
FLAPS
PARKING BRAKE VERIFY OFF

LANDING

GO-AROUND ALT/HDG SET
CABIN CREW READY
LANDING GEAR CHECK DOWN
ECAM MEMO LDG NO BLUE

GO AROUND

THRUST TO/GA
THRUST FLX MCT
SOFT GA VERIFY
PERFORM CLIMB-OUT CHECKLIST
FUEL CHECK
CALCULATE LDG PERF s INIT IN MCDU
PERFORM APPROACH CHECKLIST
PROCEED STANDART CHECKLIST SEQUENCE

AFTER LANDING

CLOCK TIMER STOP
BRAKE FAN ON
SPOILER RETRACTED
FLAPS UP
LANDING LIGHTS RETRACTED
TAXI LIGHTS ON
STROBE AUTO
APU START
WEATHER RADAR OFF
TURNING INTO GATE LIGHTS OFF

PARKING BRAKES	SET
THRUST LEVERS.....	IDLE
ENGINES.....	OFF
FUEL PUMPS.....	OFF
BEACON LIGHTS	OFF
WING LIGHTS.....	OFF
EXT POWER	ON
APU.....	OFF
CREW OX SUPPLY	OFF
ADIRS.....	OFF
CHOCKS SET.....	PARKING BRAKE RELEASED
PROBE/WINDOW HEAT.....	OFF
PAX SIGNS	OFF
DOORS.....	DISARMED (SLIDES)
DOORS.....	OPEN
COCKPIT DOOR.....	OPEN/UNLOCKED
NAV LIGHTS	OFF
EXT POWER	OFF
BATTERIES.....	OFF