




$N_{wake} = 1$	$C_T = 0.703$	$C_P = 0.526$
$N_{wake} = 2$	$C_T = 0.678$	$C_P = 0.484$
$N_{wake} = 3$	$C_T = 0.668$	$C_P = 0.467$
$N_{wake} = 4$	$C_T = 0.662$	$C_P = 0.459$
$N_{wake} = 5$	$C_T = 0.659$	$C_P = 0.454$
$N_{wake} = 6$	$C_T = 0.657$	$C_P = 0.452$
$N_{wake} = 7$	$C_T = 0.656$	$C_P = 0.450$
$N_{wake} = 8$	$C_T = 0.656$	$C_P = 0.449$
$N_{wake} = 9$	$C_T = 0.655$	$C_P = 0.448$
$N_{wake} = 10$	$C_T = 0.655$	$C_P = 0.448$
$N_{wake} = 11$	$C_T = 0.655$	$C_P = 0.447$
$N_{wake} = 12$	$C_T = 0.654$	$C_P = 0.447$
$N_{wake} = 13$	$C_T = 0.654$	$C_P = 0.447$
$N_{wake} = 14$	$C_T = 0.654$	$C_P = 0.447$
$N_{wake} = 15$	$C_T = 0.654$	$C_P = 0.446$