5. EQUIPMENT IMAGES



Three-Zone Tube Furnace



Control Parameters Display

4. SPACER FORMATION & CROSS-SECTIONS




Figure 1 : Reference Image




Figure 2 : Simulated Result




Figure 3 : Spacer Deposition




Figure 4 : Spacer Etching

4. CD PROFILE GRAPH




Figure 5 : CD and ΔCD Variation Along the Spacer Height

5. SPACER DEPOSITION AND PATTERNING IMAGES




Figure 6 : Fin Spacer Oxide Deposition and Etching (Steps 1 and 2)




Figure 7 : P-Type Spacer Nitride Deposition (Step 4)




Figure 8 : P-Type Spacer Nitride Etching (Step 5)




Figure 9 : N-Type Spacer Nitride Deposition (Step 6)




Figure 10 : N-Type Spacer Etching (Step 7)