





Sensor Type	Advantages	Limitations
Thermal Camera	Remote detection, fast mapping	Measures only the surface; depends on emissivity
Thermistor	Very accurate, fast response	Limited temperature range, requires calibration
RTD	High accuracy and stability	More expensive, needs robust electronics
Thermocouple	wide range,robust, fast response	Less accurate, requires cold-junction compensation