First XDJ-XZ mapping for Traktor Pro 3 with JogScreens.


The jog screens require the BOME midi translator. A free trial is available in https://www.bome.com


IMPORTANT: do NOT set XDJ-XZ in the controller manager. Put the BOME device there instead!

These slides show the basic configuration for the XDJ-XZ. For more details, please see the DDJ-1000 specific guide.

For a feature demo, see the videos on: https://www.youtube.com/user/djestrela2/playlists

XDJ Config:






Laptop Config:


- Please install the XDJ-XZ driver first
- Confirm Rekordbox works correctly before going to Traktor


Proper BOME config:



Proper BOME log:

Traktor config:







DO NOT put XDJ-XZ here!!!!