



Water resistive barrier and vapor retarder needs to be placed per local code requirements.

