

Property Claim Evidence Package

Claim reference: HCE-DE-2026-005184 | Review copy

Policyholder Eva Kronenberg	Policy HOME-DE-441902
Risk address Kronenbergstr. 18, 40217 Dusseldorf	Coverage Residential contents and escape of water

Claimant declaration

Field	Declared value
Date of loss	14 May 2026, approximately 06:30
Date discovered	15 May 2026, 07:55
Reported cause	Flexible hose beneath kitchen sink failed overnight
Emergency action	Main water supply closed; plumber called immediately
Prior related loss	None declared in the last five years

Amounts submitted

Item	Supplier / basis	Amount
Emergency plumbing	RohrFix Sanitaertechnik - estimate only	EUR 740.00
Drying and remediation	RheinTrock GmbH - quotation RT-26612	EUR 8,900.00
Kitchen cabinetry	WohnForm Studio - quotation WF-1097	EUR 7,650.00
Temporary accommodation	Claimant estimate - no receipts	EUR 1,350.00
Total claimed		EUR 18,640.00

Policy snapshot

Escape-of-water damage is covered subject to a EUR 1,000 deductible. Reasonable mitigation expenses are covered. The insurer may require proof of the loss date, cause, ownership, payment, and extent of damage before settlement.

Evidence gaps requiring review
No original photographs, moisture map, paid invoices, or temporary-accommodation receipts are included. The attached German service report states a different instructed loss date and says the failure time cannot be determined.

Attachment A - low-contrast service report

German-language scan supplied by claimant; OCR expected

ROHRFIX SANITAERTECHNIK

Einsatzbericht / Arbeitsnachweis

Auftragsnummer:

RF-260515-884

Objekt:

Kronenbergstr. 18, 40217 Duesseldorf

Schadentag laut Auftrag:

13.05.2026

Einsatz vor Ort:

15.05.2026, 08:40 - 11:15 Uhr

Feststellung:

Leckage an Flexschlauch unter Spuele

Ursache:

Materialermuedung; Zeitpunkt nicht sicher feststellbar

Ausgefuehrte Arbeiten

- Wasserzufuhr geschlossen, defekten Flexschlauch ersetzt.
- Bodenfeuchte im Sockelbereich erhoeht. Messwert: 68 Digits.
- Trocknungsfirma empfohlen. Fotodokumentation beim Kunden.
- Keine Fotos diesem Bericht beigefuegt.

Unterschrift Monteur: M. Yilmaz

Unterschrift Kunde: _____

Scan-Kopie | Kontrast reduziert | Seite 1 von 1