Right-hand rule

- 1. Point index finger in the direction of electric field
- 2. Point middle finger in the direction of magnetic field
- 3. Point thumb in the direction of motion

$$X_C = \frac{1}{2\pi f C}$$

where X_C is the capacitive reactance in ohms, f is the frequency, and C is the capacitance.