						Week 1											Week 2									
						Monday		Tuesday		Wednesday		Thursday		Fri	Friday		Monday		Tuesday		Wednesday		Thursday		Friday	
Task	#	APA	CE	PD	Rig	7:30	12:00	7:30	12:00	7:30	12:00	7:30	12:00	7:30	12:00	7:30	12:00	7:30	12:00	7:30	12:00	7:30	12:00	7:30	12:00	
	Hours	# FTE	# FTE	# FTE	# FTE																					
Loading Bay																										
Receive and unload shipment	4	2			2	AP.	A-1					AP	A-2													
Remove protective panels/outer frame	8	2			2	APA-1						APA-2														
Move into Airlock, remove plastic wrag	4	2			2	APA-1						AP	A-2													
Unload PD and CE boxes/week	4				2			AP	A-2													AF	PA 1			
Replace protective panels/outer frame	8	2			2			AP	A-2													AF	PA 1			
Place load on truck for shipment	4	2			2			AP	A-2													AF	PA 1			
APA Cleanroom																										
Place APA pair on 2 process carts	16	2			2		APA-1						APA-2													
Test Wire tension	32	2						APA-1					APA-2		APA-2											
Install 40 FEMBs and perform tests	48		2									CE		-1	CE-1		CE-1		С	CE-2 CE-2		E-2	CE-2			
Install 20 PDs-2 APA Pairs	16			2										PD-1						PD-2						
Test 20 PDs	16			2												PE)-1					Р	D-2			
Place APA pair on shipping frame	16	2			2	AP.	A-2													AF	PA-1					
CE Testing Cleanroom																										
Unpack, prep and test 40 FEMBs	48		2					CE Te	esting			CE Te	esting	CE Te	esting			CE T	esting			CE T	esting	CE T	esting	
PD Testing Cleanroom																										
Unpack, prep and test 20 PDs	32			2		PD				PD						PD				PD						
Total Hours and FTE Hours	256	184	192	128	126																					
Total # FTEs		4.6	4.8	3.2	3.15																					