South Dakota
Warehouse Facility
SDSD/JPO
Labor – 10 FTE

Project Integration Director SDSD Division Head

SDWF LBNF Logistic Manager

Underground Caverns
Coordinator

The SDWF Supervisor communicates with Underground Caverns Coordinator and LBNF Logistics Manager to schedule underground hoist trips

SDWF Supervisor Lead Worker per shift 3 total FTE Riggers **Equipment Operators** 2 per shift 6 total FTE

Two 8 hour shift/day
6:00 am- 11:00pm
5 days/week
Monday-Friday
Split shift
Thurs-Sunday
8:00 am - 4:30 pm

