	Week 1														ek 1								
								Day 1				Day 2				Day 3				Day 4			
	APA							Shift 1		Shift 2		Shift 1		Shift 2		Shift 1		Shift 2		Shift 1		Shift 2	
	Task	APA	CE	Shift	HV	Riggers	Location	6:00	11:00	16:00	21:00	6:00	11:00	16:00	21:00	6:00	11:00	16:00	21:00	6:00	11:00	16:00	21:00
	APA Pair #1	# FTE		3A-3R																			
1	Move APA Pair into SAS	3				3	SAS	6	3 APA,	3 Rig													
2	Install Bot APA PD/Test	3				3	SAS		6	6	3 APA,	3 Rig											
3	Install Bot APA PD/Test	3				3	SAS				6	6	3A-3R										
4	Move APA to Work Station	3				3	SAS						6		CE Co	nsortia							
5	Cable work/Test		4				WS-1							4	4	4	4	CE					
6	Cable management/CB Cable		4				WS-1											4	2A-2R				
7	Remove Protective panels	2				2	WS-1												4	2-Sur	veyor		
8	Photogrammtry/survey	2					WS-1	2-Sur	veyor	APA,C	E,2Rig								2	2	APA,C	E,2Rig	
9	Close up Cold Box/Warm test	1	1			2	CB-1	2	2	4	4		Shifters									4	4
10	Cool Down		2				CB-1					2	2	2	2 2 Shi		fters						
11	Cold Tests		2				CB-1									2 2 Shi		Shif	ters				
12	Warm Up		2				CB-1											2	2	2	2	APA,C	E,2Rig
13	Open Cold Box -Remove	1	1			2	CB-1					۸ ۵ ۸ ۱	Dair #4									4	4
14	Move to cryostat-Position					4	Cryo					APA Pair #4											
15	Final Cable-Cryostat-in & out		4				Cryo																
16	DAQ Test		4				Cryo																
17	Deploy					4	Cryo																
18	Final Test		4				Cryo																1