JPO/SDSD Common Technical Resources Labor – 57 FTE

Project Integration Director SDSD Division Head

Underground Caverns
Coordinator

Deputy

Underground Caverns Coordinator

Underground
Two ten hour shift/day
6:00 am- 3:00am
4 days/week
Monday-Thursday
Split Shift
Thursday-Sunday

Surface Transport team loads materials on cage, pulled off cage by underground team that delivers to detector cavern

> Transport Team 3-Lead Workers 1 per shift

Riggers and
Equipment Operators
4 per shift
(2 top/2 bottom)
12 total FTE

Cryogenic
Welder Team
3 FTE

Cryogenic
Welder Tech
3 FTE

Electronic Tech
Cable/Fiber
2 FTE

Underground Installation Manager

5-Lead Workers

8-Oper/Riggers 8-Core Techs

2-Surveyors

Electrician On-Call 3 FTE

Ventilation
Plumbing
Network On-Call
3 FTE

3- Safety Officers Day/Night/Split

April 9, 2019