AI SITE HISTORY REPORT

502 Church Road, Taigum QLD

Generated 07 Apr 2026 | Lat -27.333805, Lng 153.048571 | Confidence: High

Executive Summary

The site at 502 Church Road, Taigum QLD has a distinct circular water feature visible consistently across multiple years, with historical imagery showing two pond-like water bodies on or near the site. There are also cleared areas and earth disturbances detected within the site boundaries. Additional targeted remainder-lot rescan identified further possible buried / former pond risk areas requiring field confirmation.

On-site: A prominent circular water feature candidate is present in the northeastern area of the site, surrounded by vegetation. Additional signs of disturbance including cleared soil and some fill or material piles near buildings are noted mainly on the eastern and southern parts of the site. Targeted rescan placed greater emphasis on secondary former pond / buried basin risk areas.

Adjacent / context: To the east of the site is a long linear water body/ditch adjacent to the Gateway Motorway. To the north lies Cabbage Tree Creek with natural riparian vegetation. Residential developments border the site to the south and southwest.

Site Details

Address	502 Church Road, Taigum QLD
Location source	polygon
Latitude / Longitude	-27.333805, 153.048571
Site bbox	267.6 m × 274.6 m
Context bbox	321.6 m × 328.6 m
Polygon supplied	Yes

Key Flags

Key Flag	Level	Comment
Former water features	High	Large circular pond evident historically and currently on-site with water detected in all evaluated years.
Vegetation / land change	Low	Some clearing near buildings and paths noted especially after 2011 imagery.
Fill / disturbance	Moderate	Signs of soil disturbance and material piles near eastern side of site where buildings are located.

Flag Summary

Potential Fill / Disturbance — Moderate

Signs of soil disturbance and material piles near eastern side of site where buildings are located.

Former Water Features — High

Large circular pond evident historically and currently on-site with water detected in all evaluated years.

Vegetation / Land Change	**Low**
Some clearing near buildings and paths noted especially after 2011 imagery.	

Screening Outcome

The site contains at least one stable water feature likely representing a former or current pond. Some minor to moderate soil disturbance exists near building footprints. Adjacent drainage water bodies exist but do not clearly affect site surface water. Further on-ground investigation may be needed for disturbance details.

Primary On-Site Risks

Feature	Type	Relation	Confidence	Notes
Pond B	former_pond	on_site	high	Large circular water feature with vegetated perimeter visible prominently northeast within the site. Consistently detected in recent and historical images.
Pond A	former_pond	on_site	high	Large circular pond with dense vegetation rim northeast within site, visible in 1995, 2015, 2021 images. Consistent water presence and shape.
Pond C	former_pond	on_site	medium	Cleared soil/disturbance patches west and south of the water feature, some small dirt piles or cleared earth

Adjacent Contextual Influences

Feature	Type	Relation	Confidence	Notes
water_feature_2	drainage_feature	on_site	high	Narrow elongated water body (drainage or ditch) visible adjacent to east site boundary along Gateway Motorway corridor.
Adjacent Pond 1	former_pond	adjacent	medium	Cleared and possibly graded soil area around buildings in southeast part of site with some visible piles or material accumulation.

Detailed Findings

Possible Geotechnical Implications

• Former pond signatures may indicate fill, uncontrolled fill, deep fill, soft ground, or moisture-sensitive soils.

Recommended Follow-Up

• Detailed geotechnical investigation is strongly recommended based on identified site history risks.

Supporting Imagery

current_wide_context — current

Source: mapbox_bbox_wide_context

current_context — current

Source: mapbox_bbox_context

current_subzone_nw — current

Source: mapbox_bbox_subzone

current_subzone_west — current

Source: mapbox_bbox_subzone

current_site — current

Source: mapbox_bbox_site

historical_qld_followup_1 — 1995 (1995-06-18)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_1995_60cm_9543 | Resolution: 60 2

historical_qld_followup_4 — 2015 (2015-05-30)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_2015_10cm_SISP_LGA | Resolution: 10 2

historical_qld_followup_6 — 2021 (2021-07-17)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_Urban_2021_10cm_SISP | Resolution: 10 2

Limitations & Disclaimer

- No exact capture date for current images provided.
- Historical image resolution varies, limiting fine disturbance interpretation.
- Limited detail on subsurface conditions
- Water presence in some years may vary due to seasonality

This AI site history scan is a preliminary screening tool only. It is intended to identify possible visual indicators for further professional review. It must not be relied on as a substitute for geotechnical investigation, engineering assessment, or design advice.