AI SITE HISTORY REPORT

502 Church Road, Taigum QLD

Generated 08 Apr 2026 | Lat -27.333834, Lng 153.048547 | Confidence: Medium

Executive Summary

The site and adjacent area contain visible water bodies, primarily two prominent ponds on the adjacent property to the northeast, with no clear water bodies visible on-site in the current images. Historical imagery shows the larger pond on adjacent land has remained consistent in shape and size since 1995, while the smaller pond has fluctuated somewhat. The site itself appears mostly cleared with some vegetation and earthworks but no clear pond or waterbody footprint on-site currently or historically.

On-site: No visible water bodies detected on-site currently. Site is primarily cleared land with scattered trees and some disturbance from earthworks or material piles around the central area.

Adjacent / context: Two large water bodies (ponds) northeast of the site on adjacent property show consistent presence in both current and historical imagery, with some minor changes in vegetation or water coverage. These ponds have circular to irregular morphology typical of constructed farm dams or ponds.

Site Details

Address	502 Church Road, Taigum QLD
Location source	polygon
Latitude / Longitude	-27.333834, 153.048547
Site bbox	141.9 m × 145.4 m
Context bbox	195.9 m × 199.4 m
Polygon supplied	Yes

Key Flags

Key Flag	Level	Comment
Former water features	Elevated	The two ponds show consistent water presence with some variability over decades, indicating established water features likely including former pond or dam structures.
Vegetation / land change	Low	Some clearing and earthworks present on-site in current imagery, but no major historic clearing detection since 1995.
Fill / disturbance	Moderate	Current site shows disturbed area with possible fill or construction material, visible only in current imagery.

Flag Summary

Potential Fill / Disturbance	**Moderate**
Current site shows disturbed area with possible fill or construction material, visible only in current imagery.	

Former Water Features	**Elevated**
The two ponds show consistent water presence with some variability over decades, indicating established water features likely including former pond or dam structures.	

Vegetation / Land Change	**Low**
Some clearing and earthworks present on-site in current imagery, but no major historic clearing detection since 1995.	

Screening Outcome

No on-site water bodies detected historically or currently; adjacent ponds exist with stable presence. Site disturbance visible currently but no clear historical infilled ponds. Low hydrogeologic risk flagged from water bodies for site.

Secondary On-Site Risks

Feature	Type	Relation	Confidence	Notes
Pond A	pond	on_site	high	Smaller dark water-like patch visible adjacent just north of the main pond in 1995 with partial circular shape, but no visible water or wet depression present in 2021. Possible former pond or seasonally wet feature.
Disturbance Area	disturbance	on_site	medium	Disturbed earth, cleared soil or material piles near structures on site, visible on recent imagery.
Disturbance Area	disturbance	on_site	medium	Cleared earthworks and material piles near the eastern central portion of the site; no visible water but disturbed soil and construction material apparent.

Adjacent Contextual Influences

Feature	Type	Relation	Confidence	Notes
Adjacent Pond 1	former_pond	adjacent	high	Faint irregular tonal patch with some ring-like vegetation or soil tone on north-central portion of the site seen in 1995 images but not recent, possibly indicating infilled or dry former water depression.

Detailed Findings

Visible Observations

• No on-site water bodies currently visible.

• Two large adjacent ponds northeast of the site, persistent historically.

• Current earthworks and material piles on-site.

• 1995 imagery shows multiple dark water patches and partially vegetated water edges on-site.

• 2021 imagery shows a decline in visible water extent with some former features absent or vegetated over.

Overall Change Timeline

General: Water features were more pronounced and numerous in 1995; by 2021, only the primary pond remains clearly evident.

Possible Geotechnical Implications

• Active pond areas may indicate local wetness influence and moisture variability in surrounding ground.

• Former pond signatures may indicate fill, uncontrolled fill, deep fill, soft ground, or moisture-sensitive soils.

Recommended Follow-Up

- Detailed geotechnical investigation is strongly recommended based on identified site history risks.

Supporting Imagery

current_wide_context — current

Source: mapbox_bbox_wide_context

current_context — current

Source: mapbox_bbox_context

current_subzone_nw — current

Source: mapbox_bbox_subzone

current_subzone_west — current

Source: mapbox_bbox_subzone

current_site — current

Source: mapbox_bbox_site

historical_qld_followup_1 — 1995 (1995-06-18)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_1995_60cm_9543 | Resolution: 60 2

historical_qld_followup_4 — 2015 (2015-05-30)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_2015_10cm_SISP_LGA | Resolution: 10 2

historical_qld_followup_6 — 2021 (2021-07-17)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_Urban_2021_10cm_SISP | Resolution: 10 2

Limitations & Disclaimer

- Resolution of historical imagery limits finer detail detection.
- Interpretation limited to visible surface features; no subsurface data.
- Image resolution limits detection of very faint or small secondary features. Older imagery has lower clarity.
- Imagery resolution limits precise boundary identification.
- No multispectral data available to confirm moisture or vegetation health.
- Absence of intermediate year imagery to precisely date changes between 1995 and 2021.

This AI site history scan is a preliminary screening tool only. It is intended to identify possible visual indicators for further professional review. It must not be relied on as a substitute for geotechnical investigation, engineering assessment, or design advice.