# AI SITE HISTORY REPORT

502 Church Road, Taigum QLD

Generated 08 Apr 2026 | Lot size: 11,925 m² | Confidence: High

## Executive Summary

No current on-site water bodies are clearly visible; however, historical imagery indicates former ponds or infilled wet depressions on-site. Site disturbance or possible fill-related ground modification is also visible. Adjacent off-site water features were identified and treated as contextual only.

## Assessment Boundary

Current north-up image showing the drawn lot assessment boundary used for this screening.

## Key Flags

| | |
|---|---|
| **Former Water Features** | **High** |
| Historical imagery indicates former pond or altered wet depression signatures on-site. | |
| **Fill / Disturbance** | **Elevated** |

Recent on-site disturbance and possible fill-related ground modification are visible.

## Recommendation

Historical imagery indicates former or possible former pond / wet depression signatures on-site. Detailed geotechnical investigation is strongly recommended.

## Current Site Image

North-up current imagery. Polygon shown for site reference. Any visible disturbance is highlighted only if clear.

Source: mapbox_bbox_site

## Historical Evidence

Best historical image showing the clearest former water feature evidence.

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_1995_60cm_9543 | 1995-06-18

## Later Comparison Image

Later imagery used to check whether the historical water feature remains visible or appears altered.

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_Urban_2021_10cm_SISP | 2021-07-17

## Limitations & Disclaimer

- Lower resolution of 1995 imagery limits detection of smaller or subtle features.
- Low resolution images limit detailed morphology assessment.
- Some color tonal variation may be non-water features.

This AI site history scan is a preliminary screening tool only. It is intended to identify possible visual indicators for further professional review. It must not be relied on as a substitute for geotechnical investigation, engineering assessment, or design advice.